

# Cross Creek West Dam

**MS – 03408**

Located in

City of Hernando

DeSoto County, Mississippi

## **Formal Inspection Report**

**Rainfall Data (Memphis Int Airport Gage)**

July 2021

Jones-Davis & Associates, Inc.  
Consulting Engineers / Land Surveyors  
8849 Centre Street  
Southaven, Mississippi 38671

## GUIDELINES FOR DETERMINING CONDITIONS

### CONDITIONS OBSERVED - APPLIES TO UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, PRINCIPAL SPILLWAY, AUXILIARY SPILLWAY

#### SATISFACTORY

general, this part of the structure has a good appearance, and conditions observed in this area do not appear to threaten the safety of the dam.

#### FAIR

Although general cross-section is maintained, surfaces may be irregular, eroded, rutted, spalled, or otherwise not in like new condition. Conditions in this area do not currently appear to threaten the safety of the dam.

#### POOR

Continued deterioration and/or unusual loading may threaten the safety of the dam.

#### UNSATISFACTORY

Conditions observed in this area appear to threaten the safety of the dam. Conditions observed in this area are unacceptable.

### CONDITIONS OBSERVED - APPLIES TO SEEPAGE

#### SATISFACTORY (NONE)

No evidence of uncontrolled seepage. No unexplained increase in flows from designed drains. All seepage is clear. Seepage conditions do not appear to threaten the safety of the dam.

#### FAIR

Some seepage exists at areas other than the drain outfalls, or other designed drains. No unexplained increase in flows from designed drains. All seepage is clear. Seepage conditions observed do not currently appear to threaten the safety of the dam.

#### POOR

Excessive seepage exists at areas other than drain outfalls and other designed drains. Seepage needs to be evaluated. Increased flow and/or continued deterioration in seepage conditions may threaten the safety of the dam.

#### UNSATISFACTORY

Excessive seepage conditions observed appear to threaten the safety of the dam and is unacceptable. Examples: 1) Designed drain or seepage flows have increased without increase in reservoir level. 2) Drain or seepage flows contain sediment. i.e., muddy water or particles in jar samples. 3) Widespread seepage, concentrated seepage or ponding appears to threaten the safety of the dam.

# Formal Inspection Checklist

## (For Engineers)

**DAM NAME :**Cross Creek West Dam

**DAM INVENTORY NO:** MS -03408

**OWNER:**

Land Owners Name (Per Deed): Cross Creek Home Owners Association

Address: P.O. Box 238, Hernando, Mississippi 36632

Phone #:

Email:

Primary Contact Person (if different from above): Krisite Adcock

Address: Cross Creek HOA / Keith Collins Co.  
3036 Centre Oak Way  
Germanton, TN 38138

Phone #: 901-457-4804

Email: kadcock@kiethcollinsco.com

**OPERATOR (if different from Owner):**

Name:

Address:

Phone #:

Email:

**DATE(S) OF INSPECTION:** 5 June 2021

## INSPECTION PERSONNEL (include contact information)

### Mississippi Licensed Professional Engineer(s):

<u>Name</u>	<u>Affiliation</u>	<u>Area of Expertise</u>
Dewey L. Jones, P.E., P.L.S. Ph cell (901)-232-2022 (e-mail: deweyleejones1948@gmail.com)	Jones-Davis & Associates, Inc.	Hydraulics, Hydrology & Design Water Control Structures

MULTIDISCIPLINARY: I am experienced in the technical disciplines or I am working with other professionals experienced in the technical disciplines to properly inspect this dam and appurtenant works. Technical disciplines, in addition to the general civil engineering, may include geotechnical, geological, hydrologic, structural, and mechanical.

☒ Yes ☐ No Comment:

### Other technical expert(s) and advisors(s):

<u>Name</u>	<u>Affiliation</u>	<u>Area of Expertise</u>
-------------	--------------------	--------------------------

### State Representative(s):

<u>Name</u>	<u>Affiliation</u>
-------------	--------------------

### Dam Owner Representative(s):

<u>Name</u>	<u>Affiliation</u>
-------------	--------------------

### Others:

<u>Name</u>	<u>Affiliation</u>
-------------	--------------------



## GENERAL INFORMATION

Weather Conditions (including rainfall within previous 14 days): Warm and Sunny. Previous rainfall occurred on the 26<sup>th</sup>, 28<sup>th</sup> and 29<sup>th</sup> in the amounts of 0.19 and 0.38 inches and a trace respectively, additional rainfall occurred on the 1<sup>st</sup> and 2<sup>nd</sup> of June in the amounts of 1.18 and 0.04 inches respectively with traces of rain on the 3<sup>rd</sup> and 4<sup>th</sup>. See attached National Weather Service Memphis Climate Data sheets in NWS Climate Data appendix.

County: DeSoto

Stream Name: Un-Named Trib to Hurricane Cr.

Tributary of: Coldwater River

Latitude (N): 34°-50'-41"

Longitude (W): 89°-59'-34"

Purpose of Dam: Recreation and Development Enhancement

Hazard Classification: High

Drainage Area (sq. mi.): 0.088

Height of Dam (ft): 19.2

Length (ft): 350

Normal Surface (ac): 5.6

Normal Capacity (ac-ft): 44

Maximum Surface (ac): 6.1

Maximum Capacity (ac-ft): 50

Normal Reservoir Elevation (ft): 322.2

Reservoir Elevation at time of inspection (ft): 322.2+/-

## SPILLWAY SYSTEM

Type of spillway (riser and conduit, concrete chute, vegetated earthen, etc.)

Principal: Concrete weir with earthen side slopes and grouted riprap chute

Auxiliary (Emergency): N/A

Principal Spillway Capacity (inches/24 hours & storm distribution): 221<sup>(1)</sup>, No information available on 24-hour volume or distribution

Auxiliary (Emergency) Spillway Capacity (inches/24 hours & storm distribution): N/A

- (1) Reference MDEQ Letter dated 30 January 2009, "Those dams which have a Hydrologic and Hydraulic (H&H) analysis that has been approved by the Division of Dam Safety will not require any additional H&H analysis in subsequent Formal Inspections unless the

dam or lake have been significantly modified." Therefore, all reference to H&H data in this Inspection Report are based on the 2007 Inspection Report.

**Note:** If you do not understand what is meant by the above questions please engage the services of a professional who can assist you. These questions are not meant to capture the spillway capacity in cfs, as this data is irrelevant in determining the dams overall ability to pass the extreme precipitation event (% of the PMP) as required by the Regulations. If there are more than two spillways, please add an additional item. **A formal inspection will not be approved by the Dam Safety Division unless this section is completed.**

Are the spillway(s) adequate for this classification of dam (see the dam safety regulations 11 Miss. Admin. Code Pt. 7, Ch. 3 for definition of Probable Maximum Precipitation – PMP – and what amount of PMP must be handled by the different spillways)?

Principal: Yes ☒ No ☐

Auxiliary(Emergency): Yes ☐ No ☐

Above indication based on 2007 Inspection Report

If not, what percent of the total PMP will the combined spillways pass (%)? 95 % noted in 2007 Formal Inspection Report as acceptable.

Or, note date and author of hydrologic and hydraulic report evaluating spillway capacity:  
14 September 2007 by John S. Wilson, P.E.

Major changes to the dam or watershed since preparation of last report that may affect spillway adequacy? (Yes / No, if yes then describe changes): Unknown, the levee grade was increased as part of deficiencies noted in the 2007 Formal Inspection. It is unknown as to whether the H&H data in the 2007 Formal Inspection reflected this change.

## HISTORY

Date Constructed: 1997 +/-

Date(s) Reconstructed: 2007  
Modified per Inspection Report

Designer: Smith Engineering, Southaven, MS

Constructed by: Unknown

## PREVIOUS INSPECTIONS (date of)

Last Owner's Inspection: Unknown

Last Formal Inspection: March 2016

### **EMERGENCY ACTION PLAN**

Date of Last Approved Plan (when the plan was last distributed to the EAP holders): November 2007

Date of Last Revision: February 2016, Updated to new Format, Reviewed this Inspection

Is the notification flowchart complete and current? Yes

Is the emergency materials and equipment information current? Yes

When was the plan last tested? Was this test a table top exercise or a full scale exercise? Unknown

### **DOWNSTREAM HAZARD CLASSIFICATIONS**

Present Hazard Classification: High

Changes in Downstream Land Use and Habitation since last inspection: None noted based on GIS data (2019) and limits noted in 2016 EAP.

Is present Classification appropriate? Yes

### **OPERATION AND MAINTENANCE**

Date of Operation and Maintenance Plan: 2007

Are instructions adequate? Yes

Do operating personnel follow instructions? Unknown

What are operating personnel capabilities? Removal of minor debris at spillways, other maintenance is contracted for.

## **PROJECT RECORD REVIEW**

Date of file review: July 2021

Description of previous deficiencies noted and corrective actions taken (if so, when?):

### **2016 Inspection**

Maintenance:

- Area of thin or bare vegetative cover should be re-seeded and fertilized or sodded on the upstream slope east and west of the spillway. The downed trees on the west upstream slope should be removed along with downed trees on the lower end of the spillway chute. Downed trees have been removed bare areas still exist.

Changes in maintenance:

- No recommended changes continue to monitor for seepage along the downstream embankment toe of embankment and encroachment of vegetative growth at lower end of spillway chute. Ongoing by HOA.

Repairs within one year:

- None noted other than the maintenance items noted above. Ongoing by HOA,

Studies:

- None at the present time.

### **2013 Inspection**

Items noted included that adequate maintenance was being performed. Next formal inspection should address woody growth along the toe of the dam. Also, the original hydrologic and hydraulic analysis should be reviewed to determine if the depressed area at the east end of the dam was included in the analysis. Actions by the HOA are unknown as to checking the original analysis. Maintenance activities have been maintained.

### **2010 Inspection**

Items noted included the establishment of vegetative cover on the upstream slope east of the spillway, removal of two tree trunks at the spillway entrance and removal of vegetation along the downstream toe of the embankment west of the spillway.

Actions by the HOA addressed the first two items. Removal of the tree growth is still in future. Establishment of vegetative remains to be completed.

### **2007 Inspection**

Immediate actions noted were downstream area of the spillway should be repaired as soon as possible, top of the dam should be raised 1.6 feet, trees along the waterline and in the embankment area should be removed, trees on the downstream slope within 20 LF of the toe should be removed and continue monitoring of the toe area for seepage is recommended. Long term items noted were the construction of a stilling basin/scour pad. Also, the additional studies were in regard to the incorporation of any changes in downstream conditions. Action

taken by the HOA include, raising the top of dam elevation, removal of upstream trees and vegetation, repair and refurbishment of the spillway chute with riprap and grouted sections, removal of trees affecting the spillway chute. Monitoring of the embankment slope for seepage is ongoing.



## EXAMINATION OF EMBANKMENT DAMS

### DESCRIPTION OF STRUCTURE

Embankment Material: Earthen Embankment of native materials.

Cutoff Type (If Known): Unknown

Impervious Core (If Known):   Unknown

Internal Drainage System (Yes / No?) If yes, describe:   Unknown

Any Signs of Movement (Horizontal and Vertical Alignment)?   None Observed

Miscellaneous: Top of levee was raised following the 2007 Inspection Report.

### CREST

Width of Crest: 10 feet

Problems:

☒ None ☐ Ruts or Puddles ☐ Erosion ☐ Cracks with Displacement ☐ Sinkholes ☐ Not Wide Enough ☐ Low Area ☐ Misalignment ☐ Inadequate Surface Drainage ☐ Trees, Brush, Briars  
☐ Other:

If Trees, Brush, Briars is checked above please describe the nature and extent of vegetation on the dam?

Comments: Embankment ties into natural ground, no seepage was noted. No visible settlement was noted. See Photos No's 3,8,9 and 10. Private ownership across part of the dam embankment.

Overall Condition:

☒ Satisfactory  
☐ Fair  
☐ Poor  
☐ Unsatisfactory

## UPSTREAM SLOPE

Slope (H:V): 2:1

Problems:

- ☐ None ☐ Riprap - Missing, Sparse, Displaced, Weathered ☐ Wave Erosion-with Scarps  
☐ Cracks-with Displacement ☐ Sinkhole ☐ Appears Too Steep ☐ Depressions or Bulges  
☐ Slides ☐ Animal Burrows ☐ Trees, Brush, Briars  
☒ Other: Bare areas exist on upstream slope and are in need of re-seeding or sodding

If Trees, Brush, Briars is checked above please describe the nature and extent of vegetation on the dam?

Comments: Bare areas exist on upstream slope and are in need of re-seeding or sodding. See Photo's No.1,3,7,9 and 10. Erosion protection from wave wash has been installed.

Overall Condition:

- ☐ Satisfactory  
☒ Fair  
☐ Poor  
☐ Unsatisfactory

## DOWNSTREAM SLOPE (including groins and toe area)

Slope (H:V): 4:1

Problems:

- ☐ None ☐ Livestock Damage ☐ Erosion or Gullies ☐ Cracks with Displacement  
☐ Sinkholes ☐ Appears too Steep ☐ Depression or Bulges ☐ Slide(s) ☐ Soft Areas  
☒ Trees, Brush, Briars on dam or within 50 feet of toe ☐ Animal Burrows  
☐ Other:

If Trees, Brush, Briars is checked above please describe the nature and extent of vegetation on the dam?

Comments: Woody vegetation exists within 50 feet of the toe (see photo No. 8), good vegetative cover exists ( see photo's No. 3 & 8), minor bare areas were observed and should be addressed( see Photo's No. 1,3,5,7,and 9), : Embankment ties into natural ground, no seepage was noted.



Overall Condition:

- ☒ Satisfactory  
☐ Fair  
☐ Poor  
☐ Unsatisfactory

## UTILITIES

Utilities Installed in Embankment or Toe? None visible

- ☐ Phone/Cable ☐ Water ☐ Electrical ☐ Sewer ☐ Gas

Does the location of all utilities appear on the as-built plans for the dam?

## SEEPAGE

Problems:

- ☒ None ☐ Saturated Embankment Area ☐ Seepage Exits on Embankment ☐ Seepage Exits at Point Source ☐ Seepage Area at Toe ☐ Flow Adjacent to Outlet  
☐ Other:

Comments: No utilities visible.

Overall Condition:

- ☒ Satisfactory (None)  
☐ Fair  
☐ Poor  
☐ Unsatisfactory

Does the location of all drainage systems/filters appear on the as-built plans for the dam?

## SEEPAGE AND TOE DRAIN/RELIEF WELL FLOW

Location

Estimated Flow

Color (Turbidity)

No seepage along toe of the embankment was observed. No relief wells exist.

## EXAMINATION OF SPILLWAYS AND OUTLET WORKS

### PRIMARY SPILLWAY (Fill out those sections that apply)

#### ENTRANCE CHANNEL

Description: No formal entrance channel is present. Lake outflows enter directly into principal spillway. See Photo No. 7.

Vegetation (Trees, Bushes):

Debris:

Channel Side-Slope Stability:

Slope Protection/Erosion:

Unusual Conditions:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

#### SPILLWAY CREST

Description: Concrete weir section of trapezoidal shape. See photo's No. 9 & 10.

Condition of Material: Fair, concrete is showing it's age. Joints should be refurbished.

Signs of Movement: Some see Photo No. 6

Joints: Joints remain tight; however, the joints should be re-sawed and re-caulked due to age of concrete. See Photo's No. 5 and 6.

Unusual Conditions: Debris on spillway should be removed. See Photo No.5 and 7.

Overall Condition:

- ☐ Satisfactory
- ☒ Fair
- ☐ Poor
- ☐ Unsatisfactory

## CHUTES

Description: Grouted riprap chute, see photo's 2 & 4.

Condition of Material: Good.

Signs of Movement: None visible.

Joints: N/A

Unusual Conditions: Vegetation at lower end should be removed, see photo No. 2.

Overall Condition:

- ☒ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## SPILLWAY WING WALLS

Description: N/A

Condition of Material:

Signs of Movement:

Joints:

Drains:

Unusual Conditions:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## DOWNSTREAM APRON

Description: No apron is present, outflows directly enter outlet channel, no significant was observed.

Condition of Material:

Signs of Movement:

Unusual Conditions:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## INLET RISER

Description and Material Type (i.e. HDPE, Concrete, Steel, CMP, etc.): N/A

Condition of Material:

Signs of Movement:

Joints:

Floor:

Unusual Conditions:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## CONDUIT(S)

Description and Material Type (i.e. HDPE, Concrete, Steel, CMP, etc.): N/A

When was the last video inspection of the conduit?

Condition of Material:

Signs of Movement:

Joints:

Seepage into conduit(s):

Location

Estimated Flow

Turbidity

Unusual Conditions:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## TRASH RACKS

Description: N/A

Condition of Material:

Unusual Conditions:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## GATES

Description/Type: N/A

Condition:

Protective Coating:

Leakage when gate is closed (Yes / No?):

Exercising Frequency:

Gates operated at time of Inspection?

Condition of seals:

Condition of gate controls and hoists:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## STILLING BASIN

Description: N/A, outflows directly enter outlet channel, no significant was observed.

Condition of Material:

Signs of Movement:

Erosion:

Unusual Conditions:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## OUTLET CHANNEL

Vegetation (Trees, Bushes): Outlet channel is overgrown with vegetation as would be expected in a natural channel There appears to be adequate capacity to convey outflows from the lake.

Debris: No significant blockages were observed during the inspection.

Channel Side-Slope Stability: Channel banks appear stable.

Erosion: No significant erosion was observed.

Unusual Conditions: None Observed

Overall Condition:

- ☒ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## LOW LEVEL OUTLET

Description: N/A

Condition:

Trash Rack:

Leakage:

Location

Estimated Flow

Unusual Conditions:

Was the low-level outlet operated during the inspection?

Were there difficulties operating the low-level outlet?



When was the low-level outlet last operated and did this conform with the Operation and Maintenance Procedures?

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## VALVES

Description: N/A

General Condition:

Protective Coating:

Evidence of Cavitation or Abrasion:

Leakage (Yes / No?):

Frequency of Use:

Valve operated during inspection (Yes / No?):

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## AUXILIARY (EMERGENCY) SPILLWAY

Note: For Earthen Spillways Only. If the auxiliary (emergency) spillway is not earthen please duplicate the above sections for the primary spillway here as needed. If there are more than one earthen and/or other spillway besides the primary please duplicate the appropriate sections in this report.

Description: N/A

Vegetation (Trees, Bushes):

Debris:

Channel Side-Slope Stability:

Slope Protection/Erosion:

Unusual Conditions:

Overall Condition:

- ☐ Satisfactory
- ☐ Fair
- ☐ Poor
- ☐ Unsatisfactory

## EXAMINATION OF OTHER FEATURES

### INSTRUMENTATION

List all instrumentation (i.e. weirs, piezometers, flow gauges): N/A

(A separate report including instrument location, instrument readings, instrument condition, normal readings, observations, and conclusions based upon the collected data shall be attached.)

## **RESERVOIR**

Slopes: Natural slopes

Sedimentation: Presently watershed has stabilized with no new construction ongoing. Water quality was good at the time of the inspection, see Photo No. 10.

Unusual Conditions Which May Affect Dam: None noted.

Any Other Unusual Conditions: Water quality is considered good; turbidity fluctuates during wet periods.

## **APPURTENANT STRUCTURES** (Power House, Gatehouse, Penstocks, Water Supply, Other)

Description and Condition of each: N/A

## **FOUNDATION AND GEOLOGY**

Unusual Conditions Which May Affect Dam: Unknown, no subsurface investigations were made as part of this inspection.

Cracks, Joints, Bedding Planes Which May Affect Dam or Provide Seepage Paths: Unknown, no subsurface investigations made as part of this inspection.

## CONCLUSIONS

I certify that the above dam was personally inspected by me and the conditions described herein are correct to the best of my knowledge and belief.

The following maintenance concerns should be addressed (in order of importance):

- Bare areas on upstream slope should be re-seeded and fertilized or sodded.

I recommend the following changes in maintenance:

- No recommended changes continue monitoring for seepage along toe of the embankment.

I recommend the following repairs be made within one year (in order of importance):

- Remove woody growth from lower end of spillway chute and treat remaining woody stumps.

The following long-term improvements should also be undertaken (in order of importance):

- Develop plan and implement for the removal of vegetation along toe of dam embankment to create a 50-foot buffer.
- Monitor any changes in downstream conditions.

The following studies should also be undertaken (in order of importance):

- None identified at this time.

Have the recommendations above included those from previous Inspections? Yes

Does the Emergency Action Plan or the Operation and Maintenance Procedures require revision?

- Reviewed and updated as part of this inspection.

Mississippi Licensed Professional Engineer representing the dam owner in responsible charge of the inspection:

Signature  Date 2 Aug 2021

P.E. SEAL



MISC ----&gt; 31 340

# 38 340

## =====

## NOTES:

# LAST OF SEVERAL OCCURRENCES

COLUMN 17 PEAK WIND IN M.P.H.

PRELIMINARY LOCAL CLIMATOLOGICAL DATA (WS FORM: F-6) , PAGE 2

STATION: MEMPHIS  
MONTH: MAY  
YEAR: 2021  
LATITUDE: 35 3 N  
LONGITUDE: 89 59 W

## [TEMPERATURE DATA]

## [PRECIPITATION DATA]

## SYMBOLS USED IN COLUMN 16

AVERAGE MONTHLY: 69.5  
DPTR FM NORMAL: -2.6  
HIGHEST: 89 ON 27,25  
LOWEST: 49 ON 7

TOTAL FOR MONTH: 4.01  
DPTR FM NORMAL: -1.26  
GRTST 24HR 1.53 ON 2- 3

1 = FOG OR MIST  
2 = FOG REDUCING VISIBILITY  
TO 1/4 MILE OR LESS

SNOW, ICE PELLETS, HAIL  
TOTAL MONTH: 0.0 INCH  
GRTST 24HR 0.0  
GRTST DEPTH: 0

3 = THUNDER  
4 = ICE PELLETS  
5 = HAIL  
6 = FREEZING RAIN OR DRIZZLE  
7 = DUSTSTORM OR SANDSTORM;  
VSBY 1/2 MILE OR LESS  
8 = SMOKE OR HAZE  
9 = BLOWING SNOW  
X = TORNADO

## [NO. OF DAYS WITH]

## [WEATHER - DAYS WITH]

MAX 32 OR BELOW: 0  
MAX 90 OR ABOVE: 0  
MIN 32 OR BELOW: 0  
MIN 0 OR BELOW: 0

0.01 INCH OR MORE: 10  
0.10 INCH OR MORE: 8  
0.50 INCH OR MORE: 2  
1.00 INCH OR MORE: 2

## [HDD (BASE 65) ]

TOTAL THIS MO. 30  
DPTR FM NORMAL 9  
TOTAL FM JUL 1 2888  
DPTR FM NORMAL 16

CLEAR (SCALE 0-3) 5  
PTCLDY (SCALE 4-7) 20  
CLOUDY (SCALE 8-10) 6

## [CDD (BASE 65) ]

TOTAL THIS MO. 175  
DPTR FM NORMAL -65  
TOTAL FM JAN 1 248  
DPTR FM NORMAL -89

## [PRESSURE DATA]

HIGHEST SLP 30.36 ON 22  
LOWEST SLP 29.59 ON 3

## [REMARKS]

#FINAL-05-21#

# **Cross Creek West Dam**

**MS – 03408**

Located in

City of Hernando

DeSoto County, Mississippi

## **Formal Inspection Report**

### **Photographic Documentation**

July 2021

Jones-Davis & Associates, Inc.  
Consulting Engineers / Land Surveyors  
8849 Centre Street  
Southaven, Mississippi 38671





Cross Creek West Dam – MS 03408

5 June 2021

View of downstream end of principal spillway where it enters the grouted riprap flume. Accumulated debris should be removed. Also shown is the upstream slope, top of Dam and downstream slope. Tree growth is evident along toe of the Dam.

Photo No. 5



Cross Creek West Dam – MS 03408

5 June 2021

View of entrance to principal spillway and upstream slope erosion protection.

Photo No. 7



Cross Creek West Dam – MS 03408

5 June 2021

View of joint separation on concrete section of principal spillway. Spillway is aging and joints should be refurbished.

Photo No. 6



Cross Creek West Dam – MS 03408

5 June 2021

View of downstream slope <sup>west</sup> of principal spillway. Good vegetative cover exists and is well maintained. Tree growth exists along toe of Dam.

Photo No. 8






Cross Creek West Dam – MS 03408

5 June 2021

View of upstream slope, top of dam and downstream slope on the west end of Dam. Erosion has been previously placed on upstream slope. Tree growth along toe is also shown.

Photo No. 9



Cross Creek West Dam – MS 03408

5 June 2021

View of lake area showing good water quality.

Photo No. 10



# Cross Creek West Dam

**MS – 03408**

Located in  
City of Hernando  
DeSoto County, Mississippi

## Formal Inspection Report

July 2021

RECEIVED  
AUG 03 2021  
BY OLWR

Jones-Davis & Associates, Inc.  
Consulting Engineers / Land Surveyors  
8849 Centre Street  
Southaven, Mississippi 38671

RECEIVED  
AUG 03 2021