		LL REPORT			Only:
County: Leflore		art 1	Well #:	<u> </u>	
Permit #: GW-49287	Mississippi Department	er's Log t of Environmental Quali	ty Aquifer:		
Driller: Irrigation Equipment Inc.		nd Water Resources Box 2309	E-Log #:		
Date drilling completed: 3-23-16	Jackson, M (601)	IS 39225-2309 961-5210	L	<u> </u>	
74 4 7		0-0535 (fax)	for the work	and filed w	ith the
State Law requires that this report b Department at the above address w	be prepared by the licen ithin 30 days of comple	ise holder responsible etion of drilling of the	jor the wori well or bore	s ana juea w hole.	in ne
Well Owner Informat (Landowner if borehole is not fo	tion	Well or	Borehole Lo	cation	
Owner Name: Katherine Barbour	· /	Latitude: 33 23' 59.9"	Longitud	ie: 90 13' 1	5.9'
Mailing Address: 28534 County Road	511	Method of Lat/Long (check	k one): 🔲 C	onventional S	urvey,
J		🗍 USGS quad, 🖾 Hand-			
Sidon MS	38954		14, Sec <u>29</u> T		
City State			74, UGU <u>67</u> 1	<u>.vu</u> :\ <u>16</u>	
Telephone No. <u>()</u> -		(Distance) (D	SW of	Sido	
	Well / Boret				· · · · · · · · · · · · · · · · · · ·
Date drilling started: 3-23-16 D	ate drilling completed: 3-2		126' ⊦	lole diameter	18"
		<u> </u>			
anotion of the second of second	معددها أحمارهم والشام معرفا أمممو والمع				
				· · · · ·	
lethod of dosing and volume of Chlorine	used in drilling and develo	opment: 50 PPM	ic 🗌 Neutron] Other:	
Nethod of dosing and volume of Chlorine .ogs run (check all applicable): 🛛 No log	used in drilling and develo	opment: 50 PPM	ic 🗌 Neutron] Other:	
Method of dosing and volume of Chlorine Logs run (check all applicable): 🛛 No log Name of organization running log(s):	used in drilling and develo	opment: 50 PPM		Other: d Source Hea	
Nethod of dosing and volume of Chlorine logs run (check all applicable): I No log lame of organization running log(s): Purpose of borehole (check one): I W	used in drilling and develo	opment: <u>50 PPM</u> a Ray Density Soni cal/Geological Investigation			
Aethod of dosing and volume of Chlorine Logs run (check all applicable): I No log lame of organization running log(s): Purpose of borehole (check one): I Wa	used in drilling and develo	opment: <u>50 PPM</u> a Ray Density Soni cal/Geological Investigation her (<i>describe</i>)	on 🗌 Grou	nd Source Hea	
Method of dosing and volume of Chlorine Logs run (check all applicable): 🛛 No log Name of organization running log(s): Purpose of borehole (check one): 🖾 Wa 🗌 S <i>If drilling is not rela</i>	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Ot	opment: <u>50 PPM</u> a Ray Density Soni cal/Geological Investigation her (<i>describe</i>) <i>ruction, skip the rema</i>	on	nd Source Hea	
Method of dosing and volume of Chlorine Logs run (check all applicable): 🛛 No log Name of organization running log(s): Purpose of borehole (check one): 🖾 Wa <i>If drilling is not rela</i> Purpose of Well (<i>check all applicable</i>): 🗋	used in drilling and develo run	opment: <u>50 PPM</u> a Ray Density Soni cal/Geological Investigation her (<i>describe</i>) <i>ruction, skip the rema</i>	on	nd Source Hea	
Method of dosing and volume of Chlorine Logs run (check all applicable): 🛛 No log Name of organization running log(s): Purpose of borehole (check one): 🖾 Wa ☐ S <i>If drilling is not rela</i> Purpose of Well (<i>check all applicable</i>): ☐ ☐ Other (<i>describe</i>):	used in drilling and develo	opment: <u>50 PPM</u> a Ray Density Soni cal/Geological Investigation her (<i>describe</i>) <i>ruction, skip the rema</i>	on [] Grou <i>inder of this</i> Fish Culture	nd Source Hea	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ⊠ No log Name of organization running log(s): Purpose of borehole (check one): ⊠ W □ S <i>If drilling is not rela</i> Purpose of Well (<i>check all applicable</i>): □ □ Other (<i>describe</i>): If a flowing well, method of flow regulation	used in drilling and develo	opment: <u>50 PPM</u> a Ray □ Density □ Soni cal/Geological Investigation her (<i>describe</i>) <i>ruction, skip the rema</i> blic Supply ⊠ Irrigation □ Other (describe)	on [] Grou <i>inder of this</i> Fish Culture	nd Source Hea	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ⊠ No log Name of organization running log(s): Purpose of borehole (check one): ⊠ Wa □ S <u>If drilling is not rela</u> Purpose of Well (check all applicable): □ □ Other (describe): f a flowing well, method of flow regulation	used in drilling and develo	opment: <u>50 PPM</u> a Ray □ Density □ Soni cal/Geological Investigation her (<i>describe</i>) <i>ruction, skip the rema</i> blic Supply ⊠ Irrigation □ Other (describe)	on [] Grou <i>inder of this</i> Fish Culture	nd Source Hea	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ⊠ No log Name of organization running log(s): Purpose of borehole (check one): ⊠ Wa ☐ S <i>If drilling is not rela</i> Purpose of Well (<i>check all applicable</i>): □ ☐ Other (<i>describe</i>): f a flowing well, method of flow regulation Static Water Level: _14fe	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Oti ated to water well const Home Industrial Put n: Valve eet [above or below] (check one)	opment: <u>50 PPM</u> a Ray □ Density □ Soni cal/Geological Investigation her (<i>describe</i>) <i>truction, skip the rema</i> olic Supply ⊠ Irrigation □ Other (describe) land surface Date r	on Grou <i>inder of this</i> Fish Culture neasured: <u>3</u> -	nd Source Hea block 29-16	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ⊠ No log Name of organization running log(s): Purpose of borehole (check one): ⊠ Wa ☐ S <i>If drilling is not rela</i> Purpose of Well (check all applicable): □ ☐ Other (<i>describe</i>): f a flowing well, method of flow regulation Static Water Level: _14 fe Method of Measurement (check one) ⊠ S	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Oti ated to water well const Home Industrial Put n: Valve eet [above or below]	opment: <u>50 PPM</u> a Ray □ Density □ Soni cal/Geological Investigation her (<i>describe</i>) <i>truction, skip the rema</i> olic Supply ⊠ Irrigation □ Other (describe) land surface Date r □ Air line □ Other: (<i>des</i>	on Grou <i>inder of this</i> Fish Culture neasured: <u>3</u> - <i>ccribe</i>)	nd Source Hea block 29-16	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ⊠ No log Name of organization running log(s): Purpose of borehole (check one): ⊠ Ware □ S If drilling is not relate Purpose of Well (check all applicable): □ □ Other (describe): □ Other (describe): □ a flowing well, method of flow regulation Static Water Level: 14 Method of Measurement (check one) ⊠ S Well depth: 126 Well depth: 126	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Oti ated to water well const Home Industrial Put n: Valve	opment: <u>50 PPM</u> a Ray □ Density □ Soni cal/Geological Investigation her (<i>describe</i>) <i>ruction, skip the rema</i> blic Supply ⊠ Irrigation □ Other (describe) land surface Date r □ Air line □ Other: (<i>des</i> Type of grout (<i>check one</i> ,	on ☐ Grou inder of this Fish Culture neasured: <u>3</u> - ccribe) : ☐ Neat Cen	nd Source Hea <u>block</u> 29-16 nent ⊠ Bento	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ⊠ No log Name of organization running log(s): Purpose of borehole (check one): ⊠ Wa □ S <i>If drilling is not rela</i> Purpose of Well (<i>check all applicable</i>): □ □ Other (<i>describe</i>): If a flowing well, method of flow regulation Static Water Level: _14fe Method of Measurement (check one) ⊠ S Well depth: _126 Well grouted to a of Casing length: _86feet	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Other ted to water well const Home Industrial Put n: Valve Check one) Steel tape Electric tape depth of: 10 feet Casing diameter: 10	opment: <u>50 PPM</u> a Ray □ Density □ Soni cal/Geological Investigation her (<i>describe</i>) <i>ruction, skip the rema</i> blic Supply ⊠ Irrigation □ Other (describe) land surface Date r □ Air line □ Other: (<i>des</i> Type of grout (<i>check one</i> , inches Typ	on ☐ Grou inder of this Fish Culture neasured: <u>3</u> - ccribe) : ☐ Neat Cen be of casing:	nd Source Hea block 29-16 hent 🖾 Bentor PVC	at Pump
<i>If drilling is not rela</i> Purpose of Well (<i>check all applicable</i>):	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Other ted to water well const Home Industrial Put n: Valve Check one) Steel tape Electric tape depth of: 10 Screen diameter: 10	opment: 50 PPM a Ray Density Soni cal/Geological Investigation	inder of this Fish Culture neasured: <u>3</u> cribe) Climent Centre e of casing: e of screen:	nd Source Hea block 29-16 hent ⊠ Bentor PVC PVC	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ☑ No log Name of organization running log(s): Purpose of borehole (check one): ☑ Ware □ S If drilling is not related Purpose of Well (check all applicable): □ □ Other (describe): □ Other (describe): □ Aff drilling is not related Purpose of Well (check all applicable): □ □ Other (describe): □ Other (describe): □ Aff drilling is not regulation Static Water Level: 14 Method of Measurement (check one) ☑ S Well depth: 126 Casing length: 86 Screen length: 40 Screen slot size: .050	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Ott tied to water well const Home Industrial Put n: Valve Check one) Steel tape Electric tape depth of: 10 feet Casing diameter: 10 screen diameter: 10 nches Setting depth: F	ppment: 50 PPM a Ray □ Density □ Soni cal/Geological Investigation cal/Geological Investigation fruction, skip the remain plic Supply ⊠ Irrigation □ Other (describe) Iand surface Date r □ Air line □ Other: (describe) inches Type inches Type inches Type inches Type inches Type	on ☐ Grou inder of this Fish Culture measured: ccribe) : ☐ Neat Cen be of casing: the of screen: feet to12	nd Source Hea block 29-16 ent ⊠ Bento PVC PVC 6 relooment	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ⊠ No log Name of organization running log(s): Purpose of borehole (check one): ⊠ Wa □ S <u>If drilling is not rela</u> Purpose of Well (check all applicable): □ □ Other (describe): If a flowing well, method of flow regulation Static Water Level: _14 fe Method of Measurement (check one) ⊠ S Well depth: _126 Well grouted to a d Casing length: _86 feet Screen length: _40 feet Screen slot size:050 ir Type of completion (check all applicable):	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Ott tied to water well const Home Industrial Put n: Valve Check one) Steel tape Electric tape depth of: 10 feet Casing diameter: 10 screen diameter: 10 nches Setting depth: F	opment: 50 PPM a Ray □ Density □ Soni cal/Geological Investigation cal/Geological Investigation fruction, skip the remain plic Supply ⊠ Irrigation □ Other (describe) Iand surface Date r □ Air line □ Other: (describe)	inder of this inder of this Fish Culture measured: crribe) Contrology neasured: neasured: neasured: pe of casing: pe of screen: feet to2 Natural Devi	nd Source Hea block 29-16 ent ⊠ Bento PVC PVC 6 relooment	at Pump
Method of dosing and volume of Chlorine Logs run (check all applicable): ☑ No log Name of organization running log(s): Purpose of borehole (check one): ☑ With a structure Durpose of Well (check all applicable): □ Ourpose of Well (check all applicable): □ Other (describe): Other (describe): If a flowing well, method of flow regulation Static Water Level: 14 Method of Measurement (check one) ☑ S Nell depth: 126 Casing length: 86 Screen length: 40 Feet Screen slot size: .050 If ype of completion (check all applicable):	used in drilling and develo run Electric Gamma ater Well Geotechni eismic Survey Oth ted to water well const Home Industrial Put n: Valve Cet Gabove or Belectric tape depth of: 10 feet Casing diameter: 10 Screen diameter: 10 nches Setting depth: F	opment: 50 PPM a Ray □ Density □ Soni cal/Geological Investigation cal/Geological Investigation fruction, skip the remain plic Supply ⊠ Irrigation □ Other (describe) Iand surface Date r □ Air line □ Other: (describe)	inder of this inder of this Fish Culture measured: crribe) Contrology neasured: neasured: neasured: pe of casing: pe of screen: feet to2 Natural Devi	nd Source Hea block 29-16 ent ⊠ Bento PVC PVC 6 relooment	at Pump

x 3

County: Leflore Permit #: GW-49287	Fo Well #:	r Office Use (Only:
The sketch below only required for water wells If well telescopes, show depths on sketch.	Description of formations encountered mus and boreholes, unless specifically exempted	by regulations	
Ground level	Description of Formations Encountered	From (depth) Ground level	To (depth 53
	Clay	54	53 60
	Fine Sand	61	73
	Fine Sand & Gravel Med. Sand & Gravel	74	126
	Med. Sand & Graver		120
			·
			ļ
	·····		
			+
			·
If more than one screen, show location of each on sketch			1
Sketch the property layout and include the following 1) the well location 2) any permanent structures on the property th 3) any roads, power lines, or other items that m 4) a north arrow	at may aid in locating the well		<u></u>

Landowner Name:			
HEREBY CERTIFY that the well/borehole was drilled, con	nstructed and co	Form: OLWR-SWR-1A (04/08)	,
requirements of the Mississippi Department of Environment	tal Quality and th	A Mideileinni Department of Health regulations	
if applicable, and state laws.			ceivec
0695	3-30-16		
Print Name of Responsible Licensee and License No.	Date	Signature of Licensee	

Form: OLWR-SWR-1A (4/APR 04 2016

•

	STATE W	VELL REPORT	For	63 a	se Only:
County: Leflore		Part 2	Weil #:	<u> </u>	
Permit #: GW-49287		's Completion Report		•	
Driller: Irrigation Equipment Inc.		ent of Environmental Quality	Aquifer:		
Date drilling completed: 3-23-16	P.C	D. Box 2309			
Copy information from block on Part 1		, MS 39225-2309 1) 961-5210	· · · · · · · · · · · · · · · · · · ·		
		360-0535 (fax)			
This part of the report must be completed of the report must be attached and both p Well Owner Informat	parts filed with the Depa	artment at the above address wit		of well cor	
Owner Name: Katherine Barbour		Latitude: 33 23' 59.9"	Longitu	de: <u>90 13</u>	' 15.9"
ailing Address: 28534 County Road 511		Method of Lat/Long (check one): Conventional Survey,			
		🔲 USGS quad, 🖾 Hand-hel	id GPS, 📋	Survey-gra	ide GPS
Sidon MS City State	38954 e Zip code	<u>NE</u> ¼ <u>NW</u> ¼	, Sec <u>29</u> T	<u>18N</u> R <u>1E</u>	
		Miles SV	N of		idon
- <u> </u>		(Distance) (Direc			st Town)
······	Pump Typ	e (check one)			· · · · ·
3 Submersible 🗇 Turbine 🗇 Air Lift 🗇 C	centrifugal 🔲 Flowing W	/ell 🔲 Jet 🔲 Piston 🗇 Rotarv 🗆] Other (de	scribe):	
		Rated Pump Capacity: 900 +/-			s Per Minute
This Pump (check one): New 🗌 Re					
		e (check one)			
] Electric 🗌 Diesel 🔲 Gasoline 🗌 Natur	ral Gas 🔲 Tractor PTO	U Windmill D Other (describe)	:	<u></u>	
orse Power Rating of Motor: 30	Setting Depth:	70 feet N	umber of S	tages: <u>1</u>	
Static Water Level (A): Fe Drawdown [(B) - (A)]:	Feet Below Land Surfa	ace Test Pumping Rate:		Feet Below	Land Surface
Static Water Level (A): Fe Drawdown [(B) - (A)]:	Feet Below Land Surfa	Pumping Water Level (B): ace Test Pumping Rate:		Feet Below	Land Surface
Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> [] \$	Feet Below Land Surfa Steel tape Electric ta Pump Test Data	Pumping Water Level (B): ace Test Pumping Rate: pe [] Air line [] Other (<i>describ</i> e		Feet Below	Land Surface
Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> [] \$ Measured shut in head:	Feet Below Land Surfa Steel tape Electric ta Pump Test Data	Pumping Water Level (B): ace Test Pumping Rate: pe	ə):	Feet Below Gaile	v Land Surface
Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> [] \$ Measured shut in head:	Feet Below Land Surfa Steel tape Electric ta Pump Test Data	Pumping Water Level (B): ace Test Pumping Rate: pe [] Air line [] Other (describe	ə):	Feet Below Gaile	v Land Surface
tatic Water Level (A): Fe prawdown [(B) - (A)]: lethod of measurement <i>(check one):</i> [] \$ leasured shut in head:	Feet Below Land Surfa Steel tape Electric ta Pump Test Data Feet a drawdown of	Pumping Water Level (B): ace Test Pumping Rate: pe	ə):	Feet Below Gaile	v Land Surface
Static Water Level (A): Fe Prawdown [(B) - (A)]: Method of measurement <i>(check one):</i> [] \$ Measured shut in head: Vell yielded GPM with a	Feet Below Land Surfa Steel tape Electric ta Pump Test Data Feet a drawdown of	Pumping Water Level (B): ace Test Pumping Rate: pe [] Air line [] Other (describe a for Flowing Well feet after Installation	9):	Feet Below Galk	umping
Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> S Measured shut in head: Vell yielded GPM with a	Feet Below Land Surfa Steel tape Flectric ta Pump Test Data Feet a drawdown of Meter Ir	Pumping Water Level (B): ace Test Pumping Rate: pe [] Air line [] Other (describe a for Flowing Well feet after nstallation Meter Serial Number:	e):	Feet Below Galk	umping
Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): Measured shut in head: Meter Manufacturer: Meter Model Number/Name:	Feet Below Land Surfa Steel tape Electric ta Pump Test Data Feet a drawdown of Meter Ir	Pumping Water Level (B):	9):	Feet Below Galk	umping
Static Water Level (A): Fe Drawdown [(B) - (A)]:	Feet Below Land Surfa Steel tape Pump Test Data Feet a drawdown of Meter Ir Or (AF x .001, gal x 100	Pumping Water Level (B):	e):	Feet Below Galk	umping
Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): [] 3 Measured shut in head: Meter Manufacturer: GPM with a Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date:	Feet Below Land Surfa Steel tape Electric ta Pump Test Data Feet a drawdown of Meter In or (AF x .001, gal x 100 Meter installed by:	Pumping Water Level (B):	e):	Feet Below Galk	umping
Itatic Water Level (A): Fe Irawdown [(B) - (A)]: Iethod of measurement (check one): [] 3 Ieasured shut in head: Ieasured shut in head: Ieter Manufacturer: Ieter Manufacturer: Ieter Model Number/Name: Iotalizer Register Unit and Multiplier Fact Installation Date:	Feet Below Land Surfa Steel tape □ Electric ta Pump Test Data Feet a drawdown of Meter In tor (AF x .001, gal x 100 Meter installed by: paired □ Replacement	Pumping Water Level (B):	ə):	Feet Below	umping
Static Water Level (A): Fe Drawdown [(B) - (A)]:	Feet Below Land Surfa Steel tape Pump Test Data Feet a drawdown of Meter In or (AF x .001, gal x 100 Meter installed by: paired Replacement information you are cer	Pumping Water Level (B):	e):	Feet Below	umping
Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date: Is This Meter (check one):	Feet Below Land Surfa Steel tape □ Electric ta Pump Test Data Feet a drawdown of Meter In or (AF x .001, gal x 100 Meter installed by: paired □ Replacement information you are cert tural wells, a list of apprent	Pumping Water Level (B):	e):	Feet Below	umping
Static Water Level (A): Fe Drawdown [(B) - (A)]:	Feet Below Land Surfa Steel tape □ Electric ta Pump Test Data Feet a drawdown of Meter In or (AF x .001, gal x 100 Meter installed by: paired □ Replacement information you are cert tural wells, a list of apprent	Pumping Water Level (B):	e):	Feet Below	umping
Static Water Level (A): Fe Drawdown [(B) - (A)]:	Feet Below Land Surfa Steel tape □ Electric ta Pump Test Data Feet a drawdown of Meter In or (AF x .001, gal x 100 Meter installed by: paired □ Replacement information you are cert tural wells, a list of appre- ments are true to the be	Pumping Water Level (B):	e):	Feet Below Galk hours of p	tand Surface
tatic Water Level (A): Fe rawdown [(B) - (A)]: lethod of measurement (check one): S leasured shut in head: /ell yielded GPM with a leter Manufacturer: leter Model Number/Name: otalizer Register Unit and Multiplier Fact istallation Date: This Meter (check one): New Reg Important: By submitting the above a For agricul HEREBY CERTIFY that the above state 0695	Feet Below Land Surfa Steel tape □ Electric ta Pump Test Data Feet a drawdown of Meter In or (AF x .001, gal x 100 Meter installed by: paired □ Replacement information you are cert tural wells, a list of appre- ments are true to the be	Pumping Water Level (B): ace Test Pumping Rate: pe [] Air line [] Other (describe a for Flowing Well feet after feet after nstallation Meter Serial Number: Type of Meter: 10, etc): tifying that this meter was insta roved meters is on the MDEQ w est of my knowledge. 3-30-16	e):	Feet Below Galk hours of p	tandards.
tatic Water Level (A): Fe rawdown [(B) - (A)]: lethod of measurement (check one): S leasured shut in head: /ell yielded GPM with a leter Manufacturer: leter Model Number/Name: otalizer Register Unit and Multiplier Fact istallation Date: This Meter (check one): New Reg Important: By submitting the above a For agricul HEREBY CERTIFY that the above state 0695	Feet Below Land Surfa Steel tape □ Electric ta Pump Test Data Feet a drawdown of Meter In or (AF x .001, gal x 100 Meter installed by: paired □ Replacement information you are cert tural wells, a list of appre- ments are true to the be	Pumping Water Level (B): ace Test Pumping Rate: pe [] Air line [] Other (describe a for Flowing Well feet after feet after nstallation Meter Serial Number: Type of Meter: 10, etc): tifying that this meter was insta roved meters is on the MDEQ w est of my knowledge. 3-30-16	e):	Feet Below Galk hours of p	tand Surface

• , •

•