MS DAMS Inspection Report



StateID:	Dam Name:		Hazard Class:	County:
MS01186	TUSCUMBIA WS STR NUN	MBER 8 DAM	Н	ALCORN
Inspection Type:	Inspection Date	:		
STATE		8/7/2019		
Inspectors:				
A. CUMMINGS				
Primary Spillway	Туре:			
RISER AND COND	DUIT			
Primary Spillway	Size:			
Primary Spillway	Condition:	TO BE MISSING.		
Emergency Spilly				
EARTHEN	, ,,			
Emergency Spillv	vay Size:			
Emergency Spillv	vay Condition:			
HEAVY WOODY \	/EGETATION AND BRUSH PRI	ESENT.		
Upstream Slope:				
	OWN WITH WOODY VEGETA	TION AND TALL BRUS	1 .	
Downstream Slo	·			
MOSTLY OVERGE		ATION AND TALL BRUS	SH. SOME ANIMAL	BURROWS AND MINOR SLOPE
Top of Dam:				
	EN KEPT CLEAR OF OVERGRO	WTH		
Seepage:				
NONE FOUND Outlet Channel:				
	ATE ON PSW OUTLET STRUC	TURE MISSING		
TAIN - WILTAL ON	ATE ON TOW OUTEET STRUC	TORE MISSING.		
Pictures Taken?:	Υ			
	rs/Improvements: DULD BE CLEARED OF BRUSH	AND WOODY VEGETA	ATION. GRATE SHO	ULD BE REPLACED ON PSW OUTLET
Recommendation	ns:			
Comments:				
Description of Do	ownstream Hazard:			
Inspection Stat	us: POOR	Remediation	Needed?: Y	Enforcement Needed?: N