

MS DAMS

Inspection Report

StateID:

MS03282

Dam Name:

OTOUCALOFA CREEK Y-15-1 DAM

Hazard Class:

L

County:

CALHOUN

Inspection Type:

STATE

Inspection Date:

1/26/2018

Inspectors:

A. CUMMINGS

Primary Spillway Type:

RISER AND CONDUIT

Primary Spillway Size:

Primary Spillway Condition:

GOOD

Emergency Spillway Type:

EARTHEN

Emergency Spillway Size:

Emergency Spillway Condition:

12-18 INCH DHB TREES GROWING IN EMERGENCY SPILLWAY

Upstream Slope:

12-18 INCH DBH TREES AND HEAVY BRUSH PRESENT. BEAVER DAMAGE ALSO OCCURRING.

Downstream Slope:

12-18 INCH DBH TREES AND HEAVY BRUSH PRESENT. SOME VEHICLE RUTTING ON LEFT ABUTMENT.

Top of Dam:

GOOD

Seepage:

NONE NOTED

Outlet Channel:

GOOD

Pictures Taken?:

Y

Suggested Repairs/Improvements:

CLEAR WOODY VEGETATION FROM SLOPES AND EMERGENCY SPILLWAY. REPAIR DAMAGE FROM VEHICLES AND BEAVERS.

Recommendations:

Comments:

Description of Downstream Hazard:

NONE

Inspection Status: UNSATISFACTORY

Remediation Needed?: Y

Enforcement Needed?: Y

