

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
 Office of Land and Water Resources
 P. O. Box 2309
 Jackson, MS 39225
Water Well Plugging/Decommissioning Form
 OLWR-DF-1 (04/08)



COUNTY WELL LOCATED: Hancock		WELL NUMBER: #8
PERMIT NUMBER: MS-GW-17491	DATE WELL PLUGGED: 10-28-20	
NAME OF FIRM PLUGGING WELL: Griner Drilling Service, Inc.	TELEPHONE NUMBER: 601-637-6347	
NAME AND ADDRESS OF CURRENT LANDOWNER: NASA Stennis Space Center		
WELL LOCATION: Stennis	SECTION: S7	TOWNSHIP: T8S RANGE: R16W
WELL LOCATION: LATITUDE: 30°21'35.24"N	LONGITUDE: 89°37'48.26"W	METHOD (CIRCLE ONE): <input checked="" type="radio"/> USGS QUAD <input type="radio"/> CONVENTIONAL SURVEY <input type="radio"/> GPS - HAND HELD OR SURVEY GRADE
DISTANCE: 92'	DIRECTION: West	NEAREST TOWN: Bay St. Louis OTHER LANDMARK: Endeavor Rd
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Municipal		
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL: Griner Drilling Service		
NAME OF LANDOWNER WHEN WELL WAS DRILLED: Stennis		

WELL DATA		
WELL DEPTH: 1500'	HOLE DEPTH: 1500'	
CASING DIAMETER (IN.): N/A	CASING LENGTH (FT.): N/A	TYPE OF CASING: N/A
DEPTH TO STATIC WATER LEVEL: N/A	DATE WELL COMPLETED: 10-26-20	
WHY IS THE WELL BEING ABANDONED? Drilled pilot hole. Client had yearly budget change due to pandemic.		

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)

Only a pilot hole was drilled for this well. A covid 19 shutdown caused Stennis to decide to eliminate two wells from the project. We plugged the hole using the haliburton method.

We put 780 Sacks of cement to fill hole.

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.

Charles Griner	0-184
<i>Charles H. Griner</i>	MS LICENSE NUMBER
SIGNATURE	DATE
	11-05-20