

While Drilling this hole we did not get
any red sand in circulating line -
For some reason the pressure in the bottom of
this hole caused a surge and made the
wall blow after mud for about an hour -
and filled up from the bottom with a deep red
sand