		/ELL REPORT Part 1		1
County: Humphreys Permit #: GW-49374		iller's Log	Well #: Jee [O] Aquifer:	
Permit #: <u>GW-49374</u> Driller: Irrigation Equipment, Inc.	Mississippi Departm	ent of Environmental Quality and Water Resources	E-Log #:	
Date drilling completed: 6-8-16	P.C	D. Box 2309	L-Log #	
	(60 ⁻	, MS 39225-2309 1) 961-5210		
~		360-0535 (fax)		
State Law requires that this report Department at the above address v				th the
Well Owner Information (Landowner if borehole is not f	ation	Well or Bo	prehole Location	
Owner Name: John Fouche	or a water well)	Latitude: 32 55' 41.4"	Longitude: 90 29' 39). 4 "
Mailing Address: 281 West Lakeview	/ Drive	Method of Lat/Long (check or		
	1.181			
		USGS quad, 🛛 Hand-hel		GPS
Yazoo City MS City Sta	39194 te Zip code	<u>NE</u> ½ <u>SW</u> ½,	Sec <u>34</u> T <u>13N</u> R <u>3W</u>	
Telephone No. () -		MilesSE		
		(Distance) (Direc	tion) (Nearest To	wn)
	Well / Bo	rehole Data		
Date drilling started: 6-8-16	Date drilling completed:	6-8-16 Hole depth: 12	Hole diameter:	18"
I a settion of the second of a set of	iter used for drilling S	Surface Water		
Location of the source of any surface wa	ter used for driving.			
Method of dosing and volume of Chloring	• _	elopment: 50 PPM		
Method of dosing and volume of Chloring	e used in drilling and dev		3 Noutron 🗖 Othor	<u> </u>
Method of dosing and volume of Chloring	e used in drilling and dev] Neutron 🗌 Other:	
Method of dosing and volume of Chloring Logs run (check all applicable): 🛛 No lo Name of organization running log(s):	e used in drilling and dev g run [] Electric [] Garr] Neutron 🗌 Other:	
Method of dosing and volume of Chloring	e used in drilling and dev g run [] Electric [] Garr			t Pump
Method of dosing and volume of Chloring Logs run (check all applicable): I No lo Name of organization running log(s): Purpose of borehole (check one): I N	e used in drilling and dev g run	nma Ray 🗌 Density 🔲 Sonic 🕻		t Pump
Method of dosing and volume of Chloring Logs run (check all applicable):	e used in drilling and dev g run Electric Garr Vater Well Geotect	nma Ray	Ground Source Heat	t Pump
Method of dosing and volume of Chloring Logs run (check all applicable):	e used in drilling and dev g run Electric Garr Vater Well Geotect Seismic Survey	nma Ray Density Sonic hnical/Geological Investigation Other (<i>describe</i>) hstruction, skip the remained	☐ Ground Source Heat	t Pump
Method of dosing and volume of Chloring Logs run (check all applicable): 🛛 No lo Name of organization running log(s): Purpose of borehole (check one): 🖾 W ☐ \$ <i>If drilling is not rel</i> Purpose of Well (check all applicable): [e used in drilling and dev g run Electric Garr Vater Well Geotect Seismic Survey G dated to water well con	nma Ray Density Sonic hnical/Geological Investigation Other (<i>describe</i>) <i>estruction, skip the remaind</i> Dublic Supply Irrigation Fis	Ground Source Heat	t Pump
Method of dosing and volume of Chloring Logs run (check all applicable):	e used in drilling and dev g run Electric Gam Vater Well Geotech Seismic Survey Gated to water well com	nma Ray ☐ Density ☐ Sonic [hnical/Geological Investigation Other (<i>describe</i>)	Ground Source Heat	
Method of dosing and volume of Chloring Logs run (check all applicable):	e used in drilling and dev g run	nma Ray ☐ Density ☐ Sonic ☐ hnical/Geological Investigation Other (<i>describe</i>)	☐ Ground Source Heat ler of this block h Culture	
Method of dosing and volume of Chloring Logs run (check all applicable):	e used in drilling and dev g run	nma Ray ☐ Density ☐ Sonic ☐ hnical/Geological Investigation Other (<i>describe</i>)	☐ Ground Source Heat ler of this block h Culture	
Method of dosing and volume of Chloring Logs run (check all applicable):	e used in drilling and dev g run Electric Gam Vater Well Geotech Seismic Survey Ated to water well con Home Home Industrial F n: Valve feet [above or belo (check one)	nma Ray ☐ Density ☐ Sonic [hnical/Geological Investigation Other (<i>describe</i>)	Ground Source Heat	
Method of dosing and volume of Chloring Logs run (check all applicable): ☑ No lo Name of organization running log(s): Purpose of borehole (check one): ☑ W □ If drilling is not rel Purpose of Well (check all applicable): □ □ Other (describe): If a flowing well, method of flow regulation Static Water Level: 23	e used in drilling and dev g run	nma Ray ☐ Density ☐ Sonic [hnical/Geological Investigation Other (<i>describe</i>)	Ground Source Heat	
Method of dosing and volume of Chloring Logs run (check all applicable): ☑ No lo Name of organization running log(s): Purpose of borehole (check one): ☑ W □ If drilling is not rel Purpose of Well (check all applicable): □ □ Other (describe): If a flowing well, method of flow regulation Static Water Level: 23 Method of Measurement (check one) ☑	e used in drilling and dev g run	nma Ray ☐ Density ☐ Sonic ☐ hnical/Geological Investigation Other (<i>describe</i>)	□ Ground Source Heat	ite [] M
Method of dosing and volume of Chloring Logs run (check all applicable): ☑ No lo Name of organization running log(s): Purpose of borehole (check one): ☑ W □ If drilling is not rel Purpose of Well (check all applicable): □ □ Other (describe): □ If a flowing well, method of flow regulation Static Water Level: 23 Method of Measurement (check one) ☑ Well depth: 127' Well grouted to a Casing length: 87 feet	e used in drilling and dev g run	nma Ray □ Density □ Sonic □ hnical/Geological Investigation Other (<i>describe</i>)	□ Ground Source Heat	ite 🗌 M
Method of dosing and volume of Chloring Logs run (check all applicable): 🖾 No lo Name of organization running log(s): Purpose of borehole (check one): 🖾 W <i>If drilling is not rel</i> Purpose of Well (check all applicable): [Other (describe): If a flowing well, method of flow regulation Static Water Level: 23 f Method of Measurement (check one) [Well depth: 127' Well grouted to a Casing length: 87 feet Screen length: 40 feet	e used in drilling and dev g run	nma Ray ☐ Density ☐ Sonic [nnical/Geological Investigation Other (<i>describe</i>)	□ Ground Source Heat	ite 🗆 M
Method of dosing and volume of Chloring Logs run (check all applicable): ☑ No lo Name of organization running log(s): Purpose of borehole (check one): ☑ W □ □ If drilling is not rel Purpose of Well (check all applicable): □ □ Other (describe): □ Other (describe): □ Method of Measurement (check one) ☑ Well depth: 127' Well grouted to a Casing length: 87 feet Screen length: 40 feet Screen slot size: .050 i	e used in drilling and dev g run	nma Ray ☐ Density ☐ Sonic ☐ hnical/Geological Investigation Other (<i>describe</i>)	□ Ground Source Heat	ite 🗆 M
Method of dosing and volume of Chloring Logs run (check all applicable): ☑ No lo Name of organization running log(s): Purpose of borehole (check one): ☑ W □ If drilling is not rel Purpose of Well (check all applicable): □ □ Other (describe): □ Other (describe): □ If a flowing well, method of flow regulation Static Water Level: 23 Method of Measurement (check one) ☑ Well depth: 127' Well grouted to a Casing length: 87 feet Screen length: 40 feet Screen slot size: .050 i Type of completion (check all applicable) i	e used in drilling and dev g run Electric Gam Vater Well Geotech Seismic Survey Home Home Industrial Home Industrial Feet Casing diameter: 10 Screen diameter: 10 nches Setting depth	nma Ray ☐ Density ☐ Sonic ☐ hnical/Geological Investigation Other (<i>describe</i>) <i>estruction, skip the remaind</i> Public Supply ⊠ Irrigation ☐ Fis Other (describe) w] land surface Date mea pe ☐ Air line ☐ Other: (<i>describ</i> t Type of grout (<i>check one</i>): ☐ inches Type o inches Type o From 88 fe	Ground Source Heat	ite 🗆 M
Method of dosing and volume of Chloring Logs run (check all applicable): ☑ No lo Name of organization running log(s): Purpose of borehole (check one): ☑ W □ f drilling is not rel Purpose of Well (check all applicable): □ □ Other (describe): □ Other (describe): If a flowing well, method of flow regulation Static Water Level: 23 Method of Measurement (check one) ☑ Well depth: 127' Well grouted to a Casing length: 87 feet Screen length: 40 feet Screen slot size: .050 i Type of completion (check all applicable): i □ Other (describe):	e used in drilling and dev g run Electric Gam Vater Well Geotech Seismic Survey Atted to water well com Home Home Industrial Home Industrial Feet Geoteck one) Steel tape Electric tap depth of: 10 fee Casing diameter: 10 Screen diameter: 10 nches Setting depth: Electric Feet	nma Ray ☐ Density ☐ Sonic ☐ hnical/Geological Investigation Other (<i>describe</i>)	Ground Source Heat	ite 🗆 M

۰ I

County: Humphreys Permit #: GW-49374			For Well #:	Office Use (Only:
The sketch below only required		Description of formations encou and boreholes, unless specificall	<u>ntered must</u> v exempted l	<u>be provided for al</u> by regulations	<u>II wells</u>
Ground level		Description of Formations Enc	ountered	From (depth)	To (depth)
	······	Clay		Ground level	34
		Fine Sand		35	51
		Fine Sand & Gravel Med. Sand & Gravel		52 59	58 127
If more than one screen, show					
Sketch the property layout 1) the well location 2) any permanent stru 3) any roads, power li 4) a north arrow	uctures on the property that may	aid in locating the well in locating the property and the w	vell		

I HEREBY CERTIFY that the well/borehole was drilled, constructed, and completed in accordance with all applicable requirements of the Mississippi Department of Environmental Quality and the Mississippi Department of Health regulations,

9-2-16

Date

By OLME

eive

Form: OLWR-SWR-1A (04/08)

Signature of Licensee

Print Name of Responsible Licensee and License No.

Landowner Name:

0695

if applicable, and state laws.

ş

1

c

	STATE W	VELL REPORT	For O	ffice U	Jse Only:
County: Humphreys		Part 2	Well #:	LI	21
Permit #: GW-49374		r's Completion Report nent of Environmental Quality			•••
Driller: Irrigation Equipment, Inc.	Office of Land	and Water Resources	Aquifer:		
Date drilling completed: 6-8-16		D. Box 2309 , MS 39225-2309			
Copy information from block on Part 1	(60	1) 961-5210 360-0535 (fax)			
	· · ·				
This part of the report must be complete of the report must be attached and both					
Well Owner Informa	ition		I Location		
Owner Name: John Fouche		Latitude: 32 55' 41.4"	Longitude	: 90 2	9' 39.4"
Mailing Address: 281 West Lakeview	Drive	Method of Lat/Long (check or		nucration	
		Method of Lat/Long (check or	ie). 🖸 CO	nvention	iai Survey,
		🔲 USGS quad, 🖾 Hand-hel	i GPS, 🔲 S	urvey-gr	ade GPS
Yazoo City MS		<u>NE</u> ¼ <u>SW</u> ¼,	Sec <u>34</u> T <u>13</u>	N R <u>3W</u>	-
City Stat	e Zip code				
Telephone No. () -		(Distance) (Direct			ouise est Town)
	Pump Tup	e (check one)			
⊠ Submersible □ Turbine □ Air Lift □ (Other (dee	wih-1	
		/ell [_] Jet [_] Piston [_] Rotary [_] Rated Pump Capacity: 600+/-		-	
Is This Pump (check one): New CRe				Gallo	ns Per Minute
Horse Power Rating of Motor: 15 Date Well Tested:		70 feet Normal feet feet Normal feet Norma			
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]:	Pump Test Data for tet Below Land Surface Feet Below Land Surfa Steel tape Electric ta	or Non Flowing Well Duration of Pump Test <i>(minim</i> Pumping Water Level (B): Ice Test Pumping Rate: pe _ Air line _ Other <i>(describe</i>	um 4 hours) Fe	: eet Belov Gall	Hou w Land Surfac ons Per Minu
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i>	Pump Test Data for the Below Land Surface Feet Below Land Surfa Steel tape Electric tap Pump Test Data	or Non Flowing Well Duration of Pump Test <i>(minim</i> Pumping Water Level (B): ice Test Pumping Rate:	um 4 hours) Fe	: eet Belov Gall	Hour W Land Surfact ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> Measured shut in head:	Pump Test Data for eet Below Land Surface Feet Below Land Surfa Steel tape Electric tap Pump Test Data Feet	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): ice Test Pumping Rate: pe [] Air line [] Other (describe a for Flowing Well	um 4 hours) Fe):	: Gall	Hour w Land Surfac ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> Measured shut in head:	Pump Test Data for eet Below Land Surface Feet Below Land Surfa Steel tape Electric tap Pump Test Data Feet	or Non Flowing Well Duration of Pump Test <i>(minim</i> Pumping Water Level (B): Ice Test Pumping Rate: pe _ Air line _ Other <i>(describe</i>	um 4 hours) Fe):	: Gall	Hour w Land Surfac ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> Measured shut in head:	Pump Test Data for tet Below Land Surface Feet Below Land Surfa Steel tape Electric tap Pump Test Data Feet a drawdown of	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): nce Test Pumping Rate: pe [] Air line [] Other (describe a for Flowing Well feet after	um 4 hours) Fe):	: Gall	Hour w Land Surfac ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> [] Measured shut in head: Well yielded GPM with a	Pump Test Data for eet Below Land Surface Feet Below Land Surfa Steel tape Electric tap Pump Test Data Feet a drawdown of Meter In	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): nce Test Pumping Rate: pe [] Air line [] Other (describe a for Flowing Wellfeet after feet after	um 4 hours) Fe): he	eet Belov Gall	Hour w Land Surfac ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement <i>(check one):</i> Measured shut in head: Well yielded GPM with a Meter Manufacturer:	Pump Test Data for eet Below Land Surface Feet Below Land Surfa Steel tape Electric tap Pump Test Data Feet a drawdown of Meter In	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): ice Test Pumping Rate: pe [] Air line [] Other (describe a for Flowing Wellfeet after nstallation Meter Serial Number:	um 4 hours) Fe): he	: Gall	Hour v Land Surfact ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): Measured shut in head: Well yielded GPM with a Meter Manufacturer: Meter Model Number/Name:	Pump Test Data for test Below Land Surface Feet Below Land Surfa Steel tape Electric tap Pump Test Data Feet a drawdown of Meter In	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe	um 4 hours) Fe): he	: Gall ours of p	Hour w Land Surfac ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): Measured shut in head: Well yielded GPM with a Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact	Pump Test Data for eet Below Land Surface Feet Below Land Surface Steel tape Electric tap Pump Test Data Feet a drawdown of Meter In For (AF x .001, gal x 1000	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe	um 4 hours) Fe): he	eet Belov Gall	Hour w Land Surfac ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): Measured shut in head: Well yielded GPM with a Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date:	Pump Test Data for the Below Land Surface Feet Below Land Surface Feet Below Land Surfa Steel tape Electric tap Pump Test Data Pump Test Data Feet a drawdown of Meter In For (AF x .001, gal x 1000 Meter installed by:	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe Test Pumping Rate: pe Air line Other (describe a for Flowing Well feet after nstallation Meter Serial Number: 0, etc):	um 4 hours) Fe): he	eet Belov Gall	Hour w Land Surfac ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): Measured shut in head: Well yielded GPM with a Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date: Is This Meter (check one): New Reg	Pump Test Data for eet Below Land Surface Feet Below Land Surface Steel tape Electric tap Pump Test Data Feet a drawdown of Meter In For (AF x .001, gal x 1000 Meter installed by: paired Replacement	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe	um 4 hours) Fe): h	: Gall ours of p	Hour v Land Surfact ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): Measured shut in head: Well yielded GPM with a Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date: Is This Meter (check one): New Reg Important: By submitting the above in	Pump Test Data for eet Below Land Surface Feet Below Land Surface Steel tape Electric tap Pump Test Data Feet a drawdown of feet a drawdown of feet a drawdown of feet feet a drawdown of feet feet a drawdown of Meter In for (AF x .001, gal x 1000 Meter installed by: paired Replacement information you are cert	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe	um 4 hours) Fe): hu hu hu 	: Gall ours of p	Hour v Land Surfact ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): [] A Measured shut in head: Measured shut in head: Well yielded GPM with a Meter Manufacturer: Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date: Is This Meter (check one): [] New [] Reg Important: By submitting the above in For agricult	Pump Test Data for eet Below Land Surface Feet Below Land Surface Feet Below Land Surfa Steel tape [] Electric tap Pump Test Data Feet a drawdown of Feet a drawdown of feet Meter In cor (AF x .001, gal x 1000 Meter installed by: paired [] Replacement information you are cert tural wells, a list of appr	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): Pumping Water Level (B): pe Air line Other (describe a for Flowing Well	um 4 hours) Fe): hu hu hu 	: Gall ours of p	Hour v Land Surfact ons Per Minut
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): Method of measurement (check one): Method of measurement (check one): Method of measurement (check one): Method of measurement (check one): Meter Manufacturer: Meter Manufacturer: Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date: Is This Meter (check one): New Reg Important: By submitting the above i For agricul I HEREBY CERTIFY that the above state	Pump Test Data for eet Below Land Surface Feet Below Land Surface Feet Below Land Surfa Steel tape [] Electric tap Pump Test Data Feet a drawdown of Feet a drawdown of feet Meter In cor (AF x .001, gal x 1000 Meter installed by: paired [] Replacement information you are cert tural wells, a list of appr	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe	um 4 hours) Fe): hu hu hu 	cet Belov Gall ours of p	Hour
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): [] : Measured shut in head: Well yielded GPM with a Meter Manufacturer: Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date: Is This Meter (check one): [] New [] Reg Important: By submitting the above a For agricule I HEREBY CERTIFY that the above state 0695	Pump Test Data for the Below Land Surface Feet Below Land Surface Feet Below Land Surfa Steel tape □ Electric tap Pump Test Data Pump Test Data Feet a drawdown of Feet a drawdown of feet In Meter In for (AF x .001, gal x 1000 Meter installed by: paired □ Replacement information you are cert tural wells, a list of appre- ements are true to the be	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe □ Air line □ Other (describe a for Flowing Well	ed to manufa	cet Belov Gall ours of p	Hour
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): Method of measurement (check one): Method of measurement (check one): Method of measurement (check one): Method of measurement (check one): Meter Manufacturer: Meter Manufacturer: Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date: Is This Meter (check one): New Reg Important: By submitting the above i For agricul I HEREBY CERTIFY that the above state	Pump Test Data for the Below Land Surface Feet Below Land Surface Feet Below Land Surfa Steel tape □ Electric tap Pump Test Data Pump Test Data Feet a drawdown of Feet a drawdown of feet In Meter In for (AF x .001, gal x 1000 Meter installed by: paired □ Replacement information you are cert tural wells, a list of appre- ements are true to the be	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe	um 4 hours) Fe): h h ed to manufi bsite. Signature	cet Belov Gall ours of p	Hour v Land Surfactors ons Per Minut pumping tandards.
Date Well Tested: Fe Static Water Level (A): Fe Drawdown [(B) - (A)]: Method of measurement (check one): [] : Measured shut in head: Well yielded GPM with a Meter Manufacturer: Meter Manufacturer: Meter Model Number/Name: Totalizer Register Unit and Multiplier Fact Installation Date: Is This Meter (check one): [] New [] Reg Important: By submitting the above a For agricule I HEREBY CERTIFY that the above state 0695	Pump Test Data for the Below Land Surface Feet Below Land Surface Feet Below Land Surfa Steel tape □ Electric tap Pump Test Data Pump Test Data Feet a drawdown of Feet a drawdown of feet In Meter In for (AF x .001, gal x 1000 Meter installed by: paired □ Replacement information you are cert tural wells, a list of appre- ements are true to the be	or Non Flowing Well Duration of Pump Test (minim Pumping Water Level (B): pe □ Air line □ Other (describe a for Flowing Well	um 4 hours) Fe): h h ed to manufi bsite. Signature	cet Belov Gall ours of p	Hour