

If well telescopes please sketch and show depths.

GROUND LEVEL

SECTION _____

Please indicate well location X.

ADDITIONAL INFORMATION

Used solely for testing
walkout tanks and
other industrial uses.
Tested by Thiore-
Methods of Passage
High salt content
at 90.

If more than one screen,
show locations of each on sketch.