

CODED

B 18
OKTIBBEHA

WATER WELL DRILLERS LOG

Date: 5/10, 1973, Driller: Norman Edley County Okfuskee
(Name)

(1) Owner of Land: <u>Bernice Bell</u> (Name)	Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
<u>Starbuck, Min</u> (Address)	<u>Red clay</u>	<u>0</u>	<u>22</u>
(2) Location: <u>1/4, 1/4, Sec. 3</u> <u>19N</u> <u>T. 2 R. 13</u> <u>East</u>	<u>Chalk</u>	<u>22</u>	<u>780</u>
<u>8</u> miles <u>North west</u> of <u>Starbuck</u> (distance) (direction) (Nearest Town)	<u>Sand</u>	<u>780</u>	<u>900</u>
(3) Topography: <u>(Hilly)</u> (Flat) (Level)			
(4) Purpose of Well: <u>Home</u> (Domestic Irrigation Municipal, Industrial, Other)			

CODED

Information upon completion of well:

(1) Diameter 5 inches.

(2) Total Depth 900' feet.

(3) Water Level 140' feet below top of ground.

(4) Cased to 30', Size 5"

(5) Screen: Size ✓, Length ✓

(6) Were any formations sealed against pollution?
_____ yes, _____ no.

If YES depth of formation _____
Why _____

Drillers Remarks: _____

JUL 30 1973

(Use Back Side)

Well No.

100

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by a valid receipt or invoice. This ensures transparency and allows for easy verification of the data.

In the second section, the author outlines the various methods used to collect and analyze the data. This includes both primary and secondary data collection techniques. The primary data was gathered through direct observation and interviews with key stakeholders. Secondary data was obtained from existing reports and databases.

The third section details the results of the data analysis. It shows a clear trend of increasing activity over the period studied. The data indicates that the majority of transactions occur during the middle of the day, with a significant peak in the afternoon.

Finally, the document concludes with a series of recommendations based on the findings. It suggests that the current processes are largely effective but could be improved by implementing more robust data security measures. Additionally, regular audits should be conducted to ensure the accuracy of the records.

101