

Well mounted to 20' in 1967
9-185-July 1935
Revised

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

WATER RESOURCES BRANCH

WELL SCHEDULE

Date July 26, 1940 Field No. 2
Record by Wm Foster Office No. 12
Source of data Mr. G B McVay

1. Location: State Miss County Prentiss
Map Booneville Quadrangle At Baldwin Water works
SE 1/4 SE 1/4 sec. 35 T 6 S R 6 E

2. Owner: Peoples Water Service Co Address: Baldwin, Md.
Tenant: TOWN OF BALDWIN Address: Baldwin

Driller _____ Address _____

3. Topography _____

4. Elevation _____ ft. above
_____ ft. below

5. Type: Dug (drilled) driven, bored, jetted 1912

6. Depth: Rept. 596 ft. Meas. _____ ft.

7. Casing: Diam. 8 in., to _____ in., Type #1

Depth 596 ft., Finish Screen

8. Chief Aquifer Eutaw From _____ ft. to _____ ft.

Others _____

9. Water level _____ ft. rept. 19 above
_____ ft. meas. below

_____ which is _____ ft. above
_____ ft. below surface

10. Pump: Type Layne Bowler deep well turbine Capacity _____ G. M.

Power: Kind Electric Horsepower 5

11. Yield: Flow _____ G. M., Pump 85 G. M., Meas. Rept. Est.

Drawdown 5 ft. after 9 hours pumping 3,000 G. M.

12. Use: Dom., Stock, (PS) RR., Ind., Irr., Obs.

Adequacy, permanence _____

13. Quality _____ Temp 63 °F

Taste, odor, color _____ Sample No. 12-2-54

Unfit for _____


14. Remarks: (Log, Analyses, etc.) Static head reported - 62' in

Feb. 1933 when present pumps were installed

City uses AV 45,000 g.p.d. range 30,000 - 50,000 g.p.d.

Mount load July Aug & Sept.

BALDWIN QUAD




PRETISS CO
LEE CO

GUNTOWN 4.5 MI.
TUPELO 17 MI.

INTERIOR- GEOLOGICAL SURVEY, RESTON, VIRGINIA-1975
350000m.E.

ROAD CLASSIFICATION

- Primary highway, hard surface
- Secondary highway, hard surface
- Light-duty road, hard or improved surface
- Unimproved road
- Interstate Route
- U. S. Route
- State Route



(RATLIF 3252) 1 NE