

ALCORN

H 138

ELOG # 71

Bureau of Land and Water Resources  
 Southport Mall  
 P.O. Box 10631  
 Jackson, Mississippi 39209  
**WATER WELL DRILLERS LOG**

CODED

12/12 1986 Layne-Central Co., Memphis Alcorn  
 date well completed firm name county well located

LANDOWNER:	description of formations encountered	from	to
City of Corinth, MS	Clay	0	10
Highway 72 East Site	Sand and lignite	10	20
Test Hole No. 2	Clay with sand streaks	20	38
(mailing address)	Clay with sand streaks	38	46
<b>WELL LOCATION:</b>	Rock	46	47
sec. 18 T 2 N R 8 E	Clay and sand streaks	47	63
S S W	Sand lignite clay	63	110
_____ miles _____ of _____	Sand, lignite clay	110	115
(distance) (direction) (nearest town)	Sandy clay	115	204
<b>WELL PURPOSE:</b> Municipal	Rock	204	206
(home, irrigation, municipal, industrial)	Sandy clay	206	215
<b>WELL COMPLETION DATA:</b>	Rock	215	217
(1) diameter (inches) _____	Hard clay	217	254
(2) total depth (feet) _____	Rock	254	257
(3) static water level (feet) _____ below above	Sandy clay and rocks	257	331
top of ground.	Rock	331	334
(4) casing _____ (material) _____ (depth) _____	Chert	334	337
_____ (size) if telescope see back.	Rock	337	340
(5) screen _____ (length) _____ (depth to top) _____	Chert with hard streaks	340	452
_____ (size) _____ (material)			
(6) pump _____ (HP) _____ (yield gpm) _____			
_____ (type power)			
(7) electric log _____ (yes or no) _____			
_____ (organization running log)			
(8) how well bottom plugged _____			
<b>DRILLERS REMARKS:</b>			
Cemented and abandoned.			

RECEIVED

JAN 26 1987

Department of Natural Resources  
 Bureau of Land & Water Resources