

ALCORN
 H 139
 Flag # 72

Bureau of Land and Water Resources
 Southport Mall
 P.O. Box 10631
 Jackson, Mississippi 39209
WATER WELL DRILLERS LOG CODED

19 1987 Layne-Central Company Alcorn
 date well completed firm name county well located

LANDOWNER:	description of formations encountered	from	to
City of Corinth, MS Droke Road Site Test Hole No. 3 (mailing address)			
WELL LOCATION: sec. <u>7</u> T. <u>2</u> N. R. <u>3</u> E. <u>3</u> W. _____ miles _____ of _____ (distance) (direction) (nearest town) WELL PURPOSE: <u>Municipal</u> (home, irrigation, municipal, industrial) WELL COMPLETION DATA: (1) diameter (inches) <u>None</u> (2) total depth (feet) _____ (3) static water level (feet) _____ below/above top of ground. (4) casing _____ (material), _____ (depth), _____ (size) if telescope see back. (5) screen _____ (length), _____ (depth to top), _____ (size), _____ (material) (6) pump _____ (HP), _____ (yield gpm), _____ (type power) (7) electric log <u>yes</u> (yes or no), _____ State of <u>MS</u> (organization running log) (8) how well bottom plugged <u>Concrete</u> 0 to T.D.	Blue Clay	10	28
	Clay	28	32
	Fine sand & clay streaks and lignite	32	130
	Sandy clay	130	145
	Hard clay	145	155
	Sand & clay streaks	155	184
	Clay & lignite	184	213
	Sandy Clay & lignite	213	218
	Clay	218	260
	Sandy Clay	260	271
Rock	271	272	
Sandy Clay	272	332	
Hard rock	332	335	
Chert & hard streaks	335	338	
Hard rock	338	355	
Chert	355	370	
Hard rock	370	376	
Chert & hard streaks	376	385	
Rock	385	390	
Chert	390	414	
Rock	414	416	
Chert	416	427	
Rock	427	428	
Chert & hard streaks	428	454	
Rock (hard)	454	473	
RECEIVED MAR 16 1987 Department of Natural Resources Bureau of Land & Water Resources			
DRILLERS REMARKS: <u>Test Hole</u>			