

AMITE
R 2034

MISSISSIPPI DEPARTMENT OF NATURAL RESOURCES
Bureau of Land and Water Resources
Southport Mall
P.O. Box 10631
Jackson, Mississippi 39209
WATER WELL DRILLERS LOG

July 15 1985 Rever Well Service Ornith
date well completed firm name county well located

LANDOWNER:
Don. Vincent
 Rt 2 Liberty
(mailing address)

description of formations encountered	from to	
	ft	ft
<u>yellow clay</u>	<u>0</u>	<u>12</u>
<u>yellow sand</u>	<u>12</u>	<u>60</u>
<u>lumpy</u>	<u>60</u>	<u>85</u>
<u>med. coarse sand</u>	<u>80</u>	<u>100</u>

WELL LOCATION:
sec. 39 T-1 N R-3 E
2 miles north of State line
(distance) (direction) (nearest town)

WELL PURPOSE: home
(home, irrigation, municipal, industrial)

- WELL COMPLETION DATA:
- (1) diameter (inches) 4"
 - (2) total depth (feet) 100
 - (3) static water level (feet) 60' below top of ground.
 - (4) casing plastic, bottom
(material) (depth)
 - (size) If telescope see back.
 - (5) screen 5', 95'
(length) (depth to top)
 - (size) 4", plastic
(size) (material)
 - (6) pump by athis
(HP) (yield gpm)
 - chrt
(type power)
 - (7) electric log no
(yes or no)
 - (organization running log)
 - (8) how well bottom plugged backward

DRILLERS REMARKS:
old well damaged
by lightning

RECEIVED
JUN 27 1985

Department of Natural Resources
Bureau of Land & Water Resources