

Ottala  
G 26  
7-75

MISSISSIPPI  
 BOARD OF WATER COMMISSIONERS  
 416 North State Street  
 Jackson, Mississippi 39201

Co. d. e. d

WATER WELL DRILLERS LOG

July 1975 Thomastson Attala  
 date well completed film name county well located

LANDOWNER: Marvin Chapel Church  
Kosciusko, Miss.  
 (mailing address)

Description of formations encountered	from	to
<u>Red Clay</u>	<u>0</u>	<u>6</u>
<u>Pie Clay</u>	<u>6</u>	<u>12</u>
<u>5 and Rock &amp; Chalk</u>	<u>12</u>	<u>25</u>
<u>Yellow Dirty Mealy</u>	<u>25</u>	<u>65</u>
<u>5th &amp; Coarse Sand &amp; Chalk</u>	<u>65</u>	<u>80</u>

WELL LOCATION:  
 sec. 36 T. 15 N R. 7 E 13 T  
2 1/2 miles NE of Kos.  
 (distance) (direction) (nearest town)

WELL PURPOSE: Church  
 (home, irrigation, municipal, industrial)

- WELL COMPLETION DATA:
- (1) diameter (inches) 2
  - (2) total depth (feet) 80
  - (3) static water level (feet) 45 <sup>below</sup> above top of ground.
  - (4) casing PC 65  
 (material) (depth)  
2  
 (size) If telescope see back.
  - (5) screen 15 65  
 (length) (depth to top)  
2" 83/100 PC  
 (size) (material)
  - (6) pump 3/4 8  
 (HP) (yield gpm)  
elec.  
 (type power)
  - (7) electric log NO  
 (yes or no)
  - (organization running log)
  - (8) how well bottom plugged part

DRILLERS REMARKS:

RECEIVED  
 AUG 11 1975