

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
Office of Land and Water Resources
P. O. Box 2309
Jackson, MS 39225
Water Well Plugging/Decommissioning Form
OLWR-DF-1 (04/08)



COUNTY WELL LOCATED: <u>Attala</u>		WELL NUMBER: <u>M61</u>
PERMIT NUMBER: <u>MS-GW-04218</u>	DATE WELL PLUGGED: <u>5-1-21</u>	
NAME OF FIRM PLUGGING WELL: <u>Thompson Brothers</u>		TELEPHONE NUMBER: <u>601 425-0970</u>
NAME AND ADDRESS OF CURRENT LANDOWNER:		
WELL LOCATION:	SECTION: <u>20</u>	TOWNSHIP: <u>14N</u> RANGE: <u>7E</u>
WELL LOCATION: LATITUDE: <u>33° 3' 45.14"</u>	LONGITUDE: <u>89° 36' 4.04"</u>	METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY (3) GPS - HAND HELD OR SURVEY GRADE
DISTANCE: <u>0</u>	DIRECTION:	NEAREST TOWN: <u>Kosciusko</u> OTHER LANDMARK:
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): <u>Municipal</u>		
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:		
NAME OF LANDOWNER WHEN WELL WAS DRILLED: <u>Kosciusko Water & Light</u>		

WELL DATA		
WELL DEPTH: <u>445</u>	HOLE DEPTH:	
CASING DIAMETER (IN.): <u>18</u>	CASING LENGTH (FT.): <u>380</u>	TYPE OF CASING: <u>Steel</u>
DEPTH TO STATIC WATER LEVEL: <u>145</u>	DATE WELL COMPLETED:	
WHY IS THE WELL BEING ABANDONED? <u>Casing has hole in it. New well being installed.</u>		

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)

Ran tremie pipe to bottom of well.
Pumped cement slurry until well was full.
Cut casing below ground.

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.

John W Thompson
PRINT NAME

John W Thompson
SIGNATURE

0-679
MS LICENSE NUMBER

6-8-21
DATE