

ATTALA
LEAKE
T21
2-12-74

MISSISSIPPI
 BOARD OF WATER COMMISSIONERS
 416 North State Street
 Jackson, Mississippi 39201

CODED

WATER WELL DRILLERS LOG

ATTALA
Leake

Feb. 12 1974 date well completed
 Thomas & Son firm name
 county well located

LANDOWNER: David Henderson
Rt-7
Carthage, Miss.
 (mailing address)

WELL LOCATION:
 sec. 29 T. 13 (N) R. 9 (E)
7 miles SE of Kosci.
 (distance) (direction) (nearest town)

WELL PURPOSE:
 (Home, Irrigation, municipal, industrial)

WELL COMPLETION DATA:

(1) diameter (inches) 2

(2) total depth (feet) 525

(3) static water level (feet) 99 ^{below}/_{above} top of ground

(4) casing PVC, 505
 (material) (depth)
2
 (size) if telescope see back.

(5) screen 20, 505
 (length) (depth to top)
2" 8 slot PVC
 (size) (material)

(6) pump 5 HP, 20
 (HP) (yield gpm)
Elec.
 (type power)

(7) electric log NO.
 (yes or no)

(organization running log)

(8) how well bottom plugged part

description of formations encountered	from	to
Red Clay	0	20
Chalky Sand	20	30
Black Dirt	30	69
Rock & shell	69	86
Silty Black Sand	86	95
Hard Rock	95	97
Rock & shell	97	108
Green Sand	108	138
Coarse Grey Sand	138	125
Slate Rock & Blue Chalk	125	190
Dark Dirty Sand	190	210
Mostly solid slate rock	210	225
5ths Fine Sand & Chalk	225	338
Soft Grey Chalk	338	400
Hard Black Dirt	400	505
White Sand	505	525

DRILLERS REMARKS:

MISS. RD. C.

FEB 12 1974