

Benton
D49
10-30-74

MISSISSIPPI
BOARD OF WATER COMMISSIONERS CODED
416 North State Street
Jackson, Mississippi 39201

WATER WELL DRILLERS LOG

10-30- 1974 Robert W. Wilson Benton
date well completed firm name county well located

LANDOWNER:	description of formations encountered	from	to
<u>Linda Shelby</u>	<u>red clay, red sand</u>	<u>0</u>	<u>30</u>
<u>Ramar, Miss</u>	<u>red sand</u>	<u>30</u>	<u>120</u>
(mailing address)	<u>red sand, white clay, sand</u>	<u>120</u>	<u>135</u>
WELL LOCATION:	<u>red sand</u>	<u>135</u>	<u>125</u>
sec. <u>20</u> T. <u>2</u> N R. <u>1</u> E			
(distance) miles (direction) of (nearest town)			
WELL PURPOSE: (home, irrigation, municipal, industrial)			
WELL COMPLETION DATA:			
(1) diameter (inches) <u>4</u>			
(2) total depth (feet) <u>125</u>			
(3) static water level (feet) <u>105</u> below above top of ground.			
(4) casing (material) <u>121</u> (depth)			
(size) If telescope see back.			
(5) screen <u>4</u> (length) <u>121</u> (depth to top)			
(size) <u>gravel packed</u> (material)			
(6) pump <u>3/4</u> (HP) <u>10</u> (yield gpm)			
<u>electric</u> (type power)			
(7) electric log (yes or no)			
(organization running log)			
(8) how well bottom plugged <u>plastic cap</u>			
DRILLERS REMARKS:			

CODED

RECEIVED
JAN 24 1975

MISS. BD. OF WATER COMMISSIONERS