

Benton
 D 9013
 9-13-77

MISSISSIPPI
 BOARD OF WATER COMMISSIONERS
 416 North State Street
 16N Jackson, Mississippi 39201

WATER WELL DRILLERS LOG

Sept 13 1977 Billy R. Simpson BENTON
 date well completed firm name county well located

LANDOWNER:	description of formations encountered	from	to
<u>WALTER SCRUGGS</u>			
<u>LAMAR, MISS</u> (mailing address)	<u>SAND</u>	<u>8</u>	<u>118</u>
	<u>WHITE CLAY</u>	<u>118</u>	<u>128</u>
	<u>SAND + WHITE CLAY</u>	<u>128</u>	<u>180</u>
	<u>FINE SAND</u>	<u>180</u>	<u>185</u>
	<u>COARSE SAND</u>	<u>185</u>	<u>210</u>
WELL LOCATION: sec. <u>29</u> T. <u>2</u> R. <u>1</u> S W <u>1</u> miles <u>S</u> of <u>LAMAR</u> (distance) (direction) (nearest town)			
WELL PURPOSE: <u>HOME</u> (home, irrigation, municipal, industrial)			
WELL COMPLETION DATA:			
(1) diameter (inches) <u>4</u>			
(2) total depth (feet) <u>200</u>			
(3) static water level (feet) <u>135</u> below top of ground. <u>about</u>			
(4) casing <u>PVC</u> <u>194</u> (material) (depth)			
(size) if telescope see back.			
(5) screen <u>6'</u> <u>194</u> (length) (depth to top)			
<u>4"</u> <u>PVC</u> (size) (material)			
(6) pump <u>1/2</u> <u>5</u> (HP) (yield gpm)			
<u>ELEC</u> (type power)			
(7) electric log <u>NO</u> (yes or no)			
(organization running log)			
(8) how well bottom plugged <u>PVC</u> <u>CAP</u>			
DRILLERS REMARKS:			

RECEIVED

NOV 11 1977

MISS. DD. OF WATER COM