

Benton
L 2019

MISSISSIPPI DEPARTMENT OF NATURAL RESOURCES
Bureau of Land and Water Resources
Southport Mall
P.O. Box 10631
Jackson, Mississippi 39209
WATER WELL DRILLERS LOG

DEC 9 1982 Billy R. Sampson Benton
date well completed firm name county well located

LANDOWNER:
MRS FLORA ESTES
ASHLAND, MISS
(mailing address)

WELL LOCATION:
sec. 3 T 4 R 1 E
S S ASHLAND
5 miles S of (nearest town)

WELL PURPOSE: Home
(home, irrigation, municipal, industrial)

WELL COMPLETION DATA:
(1) diameter (inches) 4
(2) total depth (feet) 561
(3) static water level (feet) 22 below above top of ground.
(4) casing PVC 561 (material) (depth)
If telescope see back.
(5) screen 20 541 (length) (depth to top)
2 PVC (size) (material)
(6) pump 1/2 10 (HP) (yield gpm)
Elec (type power)
(7) electric log No (yes or no)
(organization running log)
(8) how well bottom plugged NONE

description of formations encountered	from	to
SURFACE CLAY	0	5
WHITE CLAY	5	18
LIGNITE	18	22
GRAY CLAY	22	27
ROCK	27	28
GRAY CLAY	28	53
ROCK	53	56
GRAY CLAY	56	67
ROCK	67	68
GRAY CLAY	68	75
ROCK	75	76
GRAY CLAY	76	78
ROCK	78	79
GRAY CLAY	79	100
ROCK	100	101
GRAY CLAY	101	215
Blue CLAY	215	482
LIMESTONE + SAND	482	490
Blue CLAY	490	509
LIMESTONE + SAND	509	561

DEPT. OF NATURAL RESOURCES
BUREAU OF LAND & WATER RESOURCES

DEC 13 1982

RECEIVED

DRILLERS REMARKS: