


MISSISSIPPI DEPARTMENT OF ENVIRONMENT QUALITY
 Office of Land and Water Resources
 P.O. Box 2309
 Jackson, MS 39225
 Water Well Plugging/Decommissioning Form
 OLWR-DF-1 (4/08)

6070007-01

COUNTY WELL LOCATED: Calhoun County		WELL NUMBER: K0023	
PERMIT NUMBER: MS-GW-12570		DATE WELL PLUGGED: 12-3-14	
NAME OF FIRM Mid-South Water, LLC		TELEPHONE NUMBER: (662) 843-4076	
PLUGGED WELL:			
NAME AND ADDRESS OF Duncan Hill Water Association 183 CR419, Calhoun City, MS 38916			
WELL LOCATION:	SECTION:	TOWNSHIP:	RANGE:
WELL LOCATION: LATITUDE: 33° 52' 31.4"	LONGITUDE: 89° 15' 54.2"	METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY (3) GPS - HAND HELD OR SURVEY GRADE	
DISTANCE: 100'		DIRECTION: NE of the intersection of CR419 and CR420	
NEAREST TOWN: OTHER LANDMARK:			
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Rural Water			
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL: Unknown			
NAME OF LANDOWNER WHEN WELL WAS DRILLED: Duncan Hill Water Association			

WELL DATA			
WELL DEPTH: 1875'	HOLE DEPTH 1875'		
CASING DIAMETER (IN): 6"	CASING LENGTH (FT.): 1840'	TYPE OF CASING steel	
DEPTH TO STATIC WATER LEVEL: 150'	DATE WELL COMPLETED: 3-1-1966		
WHY IS THE WELL BEING ABANDONED? Poor water quality			

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.) PWS# 70007-01 Pulled pumping equipment from the well. Ran 2" pipe to 1860'. Pumped 21yd3 of cement into the well. Cement returns obtained at ground surface. Concrete foundation removed. Casing cut off 2' below ground surface. Dressed site.
--

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS	
<u>Clayton Miller</u> PRINT NAME	<u>0-703</u> MS LICENSE NUMBER
 SIGNATURE	<u>12/16/14</u> DATE