

MISSISSIPPI DEPARTMENT OF NATURAL RESOURCES
 Bureau of Land and Water Resources
 Southport Mall
 P.O. Box 10631
 Jackson, Mississippi 39209
WATER WELL DRILLERS LOG

Carroll
F 2003

Aug 19 92 Jack Martin W Sewer Carroll
 date well completed firm name county well located

LANDOWNER	Description of formations encountered	from	to
<u>Martha M Landulata</u> <u>Landulata</u>	<u>Top clay</u>	<u>0</u>	<u>4</u>
<u>Carrollton - RA</u> (mailing address)	<u>Sand</u>	<u>4</u>	<u>32</u>
WELL LOCATION: sec. <u>32</u> T. <u>19</u> N R. <u>4</u> E <u>3</u> miles <u>SE</u> of <u>Carrollton</u> (distance) (direction) (nearest town)	<u>Mud</u>	<u>32</u>	<u>93</u>
	<u>Rock</u>	<u>93</u>	<u>94</u>
WELL PURPOSE: <u>Home</u> (home, irrigation, municipal, industrial)	<u>Sand</u>	<u>94</u>	<u>136</u>
WELL COMPLETION DATA:			
(1) diameter (inches) <u>4</u>			
(2) total depth (feet) <u>136</u>			
(3) static water level (feet) <u>100</u> below above top of ground.			
(4) casing <u>PVC</u> , <u>116</u> (material) (depth)			
(size) If telescope see back.			
(5) screen <u>20'</u> , <u>116</u> (length) (depth to top)			
<u>4"</u> , <u>PVC</u> (size) (material)			
(6) pump <u>3/4</u> , <u>10</u> (HP) (yield gpm)			
<u>Elec</u> (type power)			
(7) electric log _____ (yes or no)			
(organization running log)			
(8) how well bottom plugged <u>Cap</u>			
DRILLERS REMARKS:			

DEPT. OF NATURAL RESOURCES
 BUREAU OF LAND & WATER RESOURCES

SEP 17 1982

RECEIVED