

M 10
9-23-61

WATER WELL DRILLERS LOG


M.
3
Carroll

Date: 9-23, 1961, Driller: Jack Martin, County: ~~Robinson~~ Carroll

| (1) Owner of Land: | Description & Color of Materials Sand, Clay, Red Clay, Shell, etc. | Thick- ness Feet | Depth Feet |
|--|---|------------------------|---------------|
| Wilson & Martin (Name) Coila Mize (Address) | Red Clay | 10 | 10 |
| (2) Location: NW 1/4, NW 1/4, Sec. 22 T17R3E | Sand track | 9 | 19 |
| 3 miles East of Black Hawk (distance) (direction) (Nearest Town) | Pipe clay litter Sand | 26 | 45 |
| (3) Topography: Hilly (Hilly) (Flat) (Level) | Blue mud | 30 | 75 |
| (4) Purpose of Well: Domestic (Domestic Irrigation Municipal, Industrial, Other) | Sand | 35 | 110 |
| Information upon completion of well: | | | |
| (1) Diameter 2 inches. | | | |
| (2) Total Depth 110 feet. | | | |
| (3) Water Level 70 feet below top of ground. | | | |
| (4) Cased to _____, Size _____ | | | |
| (5) Screen: Size _____, Length _____ | | | |
| (6) Were any formations sealed against pollution? | | | |
| _____ yes, _____ no. | | | |
| If YES depth of formation _____ | | | |
| Why _____ | | | |
| Drillers Remarks: _____ | | | |
| _____ | | | |
| _____ | | | |
| _____ | | | |
| _____ | | | |
| _____ | | | |
| _____ | | | |
| _____ | | | |
| _____ | | | |

CODED

CODED



Well No.

(Use Back Side)