

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
Office of Land and Water Resources
 P. O. Box 2309
 Jackson, MS 39225
Water Well Plugging/Decommissioning Form
 OLWR-DF-1 (04/08)

019D0147

COUNTY WELL LOCATED: Choctaw		WELL NUMBER: DW-53
PERMIT NUMBER: Unknown	DATE WELL PLUGGED: 07-16-14	
NAME OF FIRM PLUGGING WELL: Terracon Consultants, Inc.	TELEPHONE NUMBER: 601-956-4467	
NAME AND ADDRESS OF CURRENT LANDOWNER: MS Lignite Mining Company 1000 McIntire Road, Ackerman, MS 39735		
WELL LOCATION:	SECTION: 27	TOWNSHIP: 18N RANGE: 10E
WELL LOCATION: LATITUDE: 33D 22M 50S	LONGITUDE: 89D 13M 58S	METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY (3) <input checked="" type="radio"/> GPS - HAND HELD OR SURVEY GRADE
DISTANCE: 5 mi DIRECTION: North NEAREST TOWN: Ackerman, MS OTHER LANDMARK: Hwy 15		
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): dewater well		
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL: H. Randal Warren		
NAME OF LANDOWNER WHEN WELL WAS DRILLED: MS Lignite Mining Company		

WELL DATA			
WELL DEPTH:	295 ft	HOLE DEPTH:	295 ft
CASING DIAMETER (IN.): 4-inch	CASING LENGTH (FT.): 250 ft	TYPE OF CASING: PVC	
DEPTH TO STATIC WATER LEVEL: 201.2	DATE WELL COMPLETED: 03/30/07		
WHY IS THE WELL BEING ABANDONED? Mining advancement			

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)

Terracon removed the pump and tubing from the well.

The well was then decommissioned by grouting the well from the bottom up using a grout pump by tremie method with a cement/bentonite grout slurry to below ground surface. The well was then cut to below ground surface and was finished with cement/bentonite grout slurry.

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.

H. Randal Warren _____

H. Randal Warren _____

0-565 _____

MS LICENSE NUMBER

09/21/16 _____

DATE