

Claburne
L 2018

MISSISSIPPI DEPARTMENT OF NATURAL RESOURCES
Bureau of Land and Water Resources
Southport Mall
P.O. Box 10631
Jackson, Mississippi 39209
WATER WELL DRILLERS LOG

May 3 1983 Reuss Well Dr Claburne
date well completed firm name county well located

LANDOWNER:	description of formations encountered	from	to
<u>Cindi Miller</u> <u>Port Gibson</u> (mailing address)			
WELL LOCATION:	<u>Brown Clay</u> <u>sand</u> <u>white chalk</u> <u>fine white sand</u> <u>Coarse sand</u>	<u>9</u> <u>19</u> <u>25</u> <u>80</u> <u>100</u>	<u>18</u> <u>45</u> <u>80</u> <u>100</u> <u>115</u>
sec <u>26</u> T <u>11</u> N R <u>2</u> E <u>1 1/2</u> miles <u>S-SE</u> of <u>Port Gibson</u> (distance) (direction) (nearest town)			
WELL PURPOSE: <u>house</u> (home, irrigation, municipal, industrial)			
WELL COMPLETION DATA:			
(1) diameter (inches) <u>4"</u>			
(2) total depth (feet) <u>115</u>			
(3) static water level (feet) <u>70</u> below top of ground.			
(4) casing <u>plastic bottom</u> (material) (depth)			
_____ if telescope see back. (size)			
(5) screen <u>5'</u> <u>100</u> (length) (depth to top)			
<u>1/2"</u> <u>plastic</u> (size) (material)			
(6) pump <u>1/2</u> <u>10</u> (HP) (yield gpm)			
<u>elect</u> (type power)			
(7) electric log <u>no</u> (yes or no)			
_____ (organization running log)			
(8) how well bottom plugged <u>back wash</u>			
DRILLERS REMARKS:			

DEPT. OF NATURAL RESOURCES
BUREAU OF LAND & WATER RESOURCES

JUL 5 1983

RECEIVED