

Coahoma Co.
G21

FIELD BORING LOG

PROJECT Hillhouse Relief Wells
 DRILL RIG Franks
 DEPTH OF WATER 11.5
 ELEVATION OF GROUND 157.62

HOLE NO. 11
 SHEET 1 OF 1
 LOCATION REMA Loro MS
 INSPECTOR _____ OPERATOR _____
 DATE 3/04/02 TABLE _____ DATE 3/04/02
 MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	3/04	20'	21'			f sand	
	"	25'	26'			f sand	
	"	30'	31'			silt	
	"	35'	36'			sandy silt	
	"	40'	41'			sandy silt	
	"	45'	46'			f sand	
	"	50'	51'			M sand	
	"	55'	56'			C sand	
	"	60'	61'			C sand	
	"	65'	66'			M w/ C sand	
	"	70'	71'			C sand	
	"	75'	76'			C sand	
	"	80'	81'			C sand	
	"	85'	86'			f sand w/ gravel	
	"	90'	91'			f sand w/ gravel	
	"	95'	96'			M sand	
	"	100'	101'			M sand	
	"	105'	106'			M sand	
	"	110'	111'			M sand w/ gravel	
	"	115'	116'			C sand	
	"	120'	121'			C sand w/ gravel	
	"	125'	126'			C sand w/ gravel	
	"	127'	128'			f sand	

RECEIVED
 JUN 05 2002

Dept. of Environmental Quality
 Office of Land & Water Resources

LMM 650
 JAN '64