

Coahoma Co.
G22

FIELD BORING LOG

HOLE NO. 12

SHEET 1 OF 1

PROJECT Hillhouse Relief Wells

LOCATION RENA LAKE MS

DRILL RIG Franks

INSPECTOR _____

OPERATOR _____

DEPTH OF WATER 20.0 DATE 5/05/02

TABLE _____

DATE 5/05/02

ELEVATION OF GROUND 157.55

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	5/05	20'	21'			silt	
"	"	25'	26'			f sand	
"	"	30'	31'			Clay	
"	"	35'	36'			f sand	
"	"	40'	41'			f sand	
"	"	45'	46'			f sand	
"	"	50'	51'			f-M sand	
"	"	55'	56'			C sand	
"	"	60'	61'			C sand	
"	"	65'	66'			C sand	
"	"	70'	71'			f-M sand	
"	"	75'	76'			M sand	
"	"	80'	81'			C sand	
"	"	85'	86'			C sand	
"	"	90'	91'			C sand & Wood fibers	
"	"	95'	96'			C sand	
"	"	100'	101'			f-C sand	
"	"	105'	106'			f-M sand	
"	"	110'	111'			M sand	
"	"	115'	116'			M sand	
"	"	120'	121'			C sand	
"	"	125'	126'			C sand w/gravel	
"	"	132'	133'			f sand	

RECEIVED

JUN 05 2002

Dept. of Environmental Quality
Office of Land & Water Resources

LMM 650
JAN '64