

Coahoma Co.
G23

FIELD BORING LOG

PROJECT Hillhouse Relief Wells

HOLE NO. 13

DRILL RIG Frank's

SHEET 1 OF 1

LOCATION RENA LAKE MS

DEPTH OF WATER 11.6

INSPECTOR _____

OPERATOR _____

ELEVATION OF GROUND 157.6

DATE 5/05/02

TABLE _____

DATE 5/05/02

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	5/05	20'	21'			f sand	
	"	25'	26'			sandy silt	
	"	30'	31'			M w/c sand	
	"	35'	36'			Clay	
	"	40'	41'			f sand	
	"	45'	46'			f sand	
	"	50'	51'			f sand	
	"	55'	56'			f sand	
	"	60'	61'			f - M sand	
	"	65'	66'			f - M sand	
	"	70'	71'			C sand	
	"	75'	76'			M sand	
	"	80'	81'			C sand	
	"	85'	86'			C sand w/ Gravel	
	"	90'	91'			C sand	
	"	95'	96'			C sand	
	"	100'	101'			C sand	
	"	105'	106'			C sand w/ Gravel	
	"	110'	111'			F - M sand	
	"	115'	116'			M sand	
	"	120'	121'			M sand	
	"	125'	126'			C sand	
	"	130'	131'			f sand	

RECEIVED

JUN 05 2002

LMM 650
JAN '64

Dept. of Environmental Quality
Office of Land & Water Resources