

Coahoma Co.
G24

FIELD BORING LOG

HOLE NO. 14

SHEET 1 OF 1

PROJECT Hillhouse Relief Wells

LOCATION Rena Lake MS

DRILL RIG Frank's

INSPECTOR

OPERATOR

DEPTH OF WATER 12 ft

DATE 3/06/02

TABLE

DATE 3/06/02

ELEVATION OF GROUND 157.6

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	3/06	20'	21'			F sand	
	"	25'	26'			F sand	
	"	30'	31'			Clay	
	"	35'	36'			F sand	
	"	40'	41'			F sand	
	"	45'	46'			F sand	
	"	50'	51'			F sand	
	"	55'	56'			F-M sand w/ Gravel	
	"	60'	61'			F-M sand	
	"	65'	66'			F-C sand	
	"	70'	71'			C sand	
	"	75'	76'			C sand	
	"	80'	81'			C sand	
	"	85'	86'			C sand	
	"	90'	91'			C sand	
	"	95'	96'			G sand	
	"	100'	101'			C sand	
	"	105'	106'			F-M sand	
	"	110'	111'			M sand w/ Gravel	
	"	115'	116'			C sand w/ Gravel	
	"	120'	121'			M sand Clay seam	
	"	125'	126'			Gravelly C sand	
	"	130'	131'			C sand w/ Gravel + sand stone	
	"	137'	138'			C sand w/ Gravel	

RECEIVED

JUN 05 2002

Dept. of Environmental Quality
Office of Land & Water Resources

LMM 650
JAN '64