



Coahoma Co.  
G25

FIELD BORING LOG

HOLE NO. 15

SHEET 1 OF 1

PROJECT Hillhouse Relief Wells

LOCATION Renalora MS

DRILL RIG Franks

INSPECTOR

OPERATOR

DEPTH OF WATER 13.5

DATE 5/11/02

TABLE

DATE 5/11/02

ELEVATION OF GROUND 157.4

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	5/11	20'	21'			f - M sand	
	"	25'	26'			<del>f - M sand</del> f sand	
	"	30'	31'			Clay	
	"	35'	36'			f sand	
	"	40'	41'			f sand	
	"	45'	46'			f sand w/silt	
	"	50'	51'			f sand	
	"	55'	56'			F - M sand	
	"	60'	61'			F - C sand	
	"	65'	66'			F - C sand	
	"	70'	71'			F - C sand	
	"	75'	76'			F - C sand	
	"	80'	81'			C - sand	
	"	85'	86'			C - sand w/ clay seam	
	"	90'	91'			C - sand	
	"	95'	96'			C - sand	
	"	100'	101'			C - sand	
	"	105'	106'			Gravelly C sand	
	"	110'	111'			C sand w/ Gravel	
	"	115'	116'			C sand w/ Gravel	
	"	120'	121'			C sand w/ Gravel	
	"	125'	126'			C sand w/ Gravel	
	"	130'	131'			F sand	
LMM 650 JAN '64		135'	136'			C sand w/ Gravel	

RECEIVED

JUN 05 2002

Dept. of Environmental Quality  
Office of Land & Water Resources