



Coahoma Co.  
G26

FIELD BORING LOG

5910

PROJECT Hillhouse Relief Wells

HOLE NO. 16

DRILL RIG Frank's

SHEET 1 OF 1

LOCATION RENA LAKE MS

DEPTH OF WATER 12 ft

DATE 5/03/02

INSPECTOR \_\_\_\_\_

OPERATOR \_\_\_\_\_

ELEVATION OF GROUND 157.5

TABLE \_\_\_\_\_

DATE 5/03/02

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	5/03	20'	21'			f - M sand	
	"	25'	26'			f sand	
	"	30'	31'			silt w/ f sand	
	"	35'	36'			f silty sand	
	"	40'	41'			f sand	
	"	45'	46'			f sand	
	"	50'	51'			f sand	
	"	55'	56'			f sand w/m sand	
	"	60'	61'			f - M sand	
	"	65'	66'			f - M sand w/ c sand & Gravel	
	"	70'	71'			C sand	
	"	75'	76'			f - M sand	
	"	80'	81'			C sand	
	"	85'	86'			C sand	
	"	90'	91'			C sand w/ lg Gravel	
	"	95'	96'			C sand w/ lg Gravel	
	"	100'	101'			M w/ C sand	
	"	105'	106'			C sand & lg Gravel	Clay Seam
	"	110'	111'			f sand w/ Gravel	
	"	115'	116'			C - f sand	
	"	120'	121'			C - f sand	
	"	125'	126'			f sand	
	"	129'	130'			f sand	

LMM 650  
JAN '64

RECEIVED

JUN 05 2002

Dept. of Environmental Quality  
Office of Land & Water Resources