

Coahoma Co.
G 28

FIELD BORING LOG

HOLE NO. 18

PROJECT Hillhouse Relief Wells

SHEET 1 OF 1

DRILL RIG Franks

LOCATION RENA Loro MS

DEPTH OF WATER 11.6

DATE 8/09/02

TABLE

OPERATOR

DATE 8/09/02

ELEVATION OF GROUND 157.05

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	8/09	20'	21'			coarse sandy silt	
	"	25'	26'			sandy silt	
	"	30'	31'			f sand	
	"	35'	36'			f sand	
	"	40'	41'			f sand	
	"	45'	46'			f sand	
	"	50'	51'			f-C sand	
	"	55'	56'			f sand	
	"	60'	61'			M sand	
	"	65'	66'			C sand	
	"	70'	71'			C sand	
	"	75'	76'			C sand	
	"	80'	81'			C sand	
	"	85'	86'			C sand w/ clay seam	
	"	90'	91'			M sand	
	"	95'	96'			C sand w/ gravel	
	"	100'	101'			f-M sand	
	"	105'	106'			f-M sand	
	"	110'	111'			f-M sand w/ C sand	
	"	115'	116'			C sand w/ gravel	
	"	120'	121'			C sand w/ gravel	
	"	125'	126'			f sand	
	"	130'	131'			f sand	
LMM 650 JAN '64		132'	133'			f-C sand w/ gravel	

RECEIVED

JUN 05 2002

Dept. of Environmental Quality
Office of Land & Water Resources