

Coahoma Co.
G29

FIELD BORING LOG

HOLE NO. 19

PROJECT Hillhouse Relief Wells

SHEET 1 OF 1

DRILL RIG Franks

LOCATION Rena Lake MS

DEPTH OF WATER 11.8

DATE 8/09/02

TABLE

INSPECTOR

OPERATOR

ELEVATION OF GROUND 156.9

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	8/09	20'	21'			f sand	
	"	25'	26'			f sand	
	"	30'	31'			f sandy silt	
	"	35'	36'			f sandy silt	
	"	40'	41'			f-M sand	
	"	45'	46'			f sand	
	"	50'	51'			f sand	
	"	55'	56'			f sand	
	"	60'	61'			M sand	
	"	65'	66'			C sand	
	"	70'	71'			C sand	
	"	75'	76'			C sand	
	"	80'	81'			gravelly C sand	
	"	85'	86'			C sand w/gravel	
	"	90'	91'			C sand w/gravel	
	"	95'	96'			C sand w/gravel	
	"	100'	101'			C sand w/gravel	
	"	105'	106'			M ^{sand} w/gravel	
	"	110'	111'			C sand w/gravel	
	"	115'	116'			C sand & gravel	
	"	120'	121'			M sand w/gravel	
	"	124'	125'			f sand	

LMM 650
JAN '64

RECEIVED
JUN 05 2002

Dept. of Environmental Quality
Office of Land & Water Resources