

Coahoma Co.
G 32

FIELD BORING LOG

HOLE NO. 22

PROJECT Hillhouse Relief Wells

SHEET _____ OF _____

DRILL RIG FRANKS

LOCATION RENA LAKE MS

DEPTH OF WATER 5.6

INSPECTOR _____

OPERATOR _____

DATE 5-11-02

TABLE _____

DATE _____

ELEVATION OF GROUND 157.82

MUD NONE

| Sample Number | Date | Sample | | Stratum | | Classification - Remarks | Type Sampler |
|---------------|------|--------|-----|---------|----|--------------------------|--------------|
| | | From | To | From | To | | |
| | | 0 | 15 | | | CLAY W/SILT SEAMS | |
| | | 15 | 16 | | | F SAND W/SILT | |
| | | 20 | 21 | | | F SAND W/SILT | |
| | | 25 | 26 | | | F SAND W/SILT | |
| | | 30 | 31 | | | F-M SAND | |
| | | 35 | 36 | | | F SILTY SAND | |
| | | 40 | 41 | | | F SILTY SAND | |
| | | 45 | 46 | | | F-M SAND | |
| | | 50 | 51 | | | F-M SAND | |
| | | 55 | 56 | | | F-M SAND | |
| | | 60 | 61 | | | F-M SAND | |
| | | 65 | 66 | | | F-M SAND | |
| | | 70 | 71 | | | F-M SAND | |
| | | 75 | 76 | | | F-C SAND W/GRVL | |
| | | 80 | 81 | | | F-C SAND W/GRVL | |
| | | 85 | 86 | | | F-M SAND W/TRACE C SAND | |
| | | 90 | 91 | | | F W/M SAND | |
| | | 95 | 96 | | | F W/M SAND | |
| | | 100 | 101 | | | F-M SAND W/GRVL | |
| | | 105 | 106 | | | F-M W/C SAND | |
| | | 110 | 111 | | | F SAND W/TR M SAND | |
| | | 115 | 116 | | | F SAND W/TR M SAND | |
| | | 120 | 121 | | | F-M SAND | |

RECEIVED

JUN 05 2002

Dept. of Environmental Quality
Office of Land & Water Resources

LMM 650
JAN '64