

Coahoma Co.
G35

FIELD BORING LOG

HOLE NO. 9

SHEET 1 OF 1

PROJECT Hillhouse Relief Wells

LOCATION REMA LAGO MS

DRILL RIG Franks

INSPECTOR _____

OPERATOR _____

DEPTH OF WATER 11.9

DATE 3/04/02

TABLE _____

DATE 3/04/02

ELEVATION OF GROUND 152.0

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	3/04	20'	21'			silty sand	
	"	25'	26'			silty sand	
	"	30'	31'			sandy silt	
	"	35'	36'			f sand	
	"	40'	41'			f sand	
	"	45'	46'			sandy silt	
	"	50'	51'			f sand	
	"	55'	56'			M sand	
	"	60'	61'			M sand	
	"	65'	66'			f sand	
	"	70'	71'			f sand	
	"	75'	76'			f-M sand	
	"	80'	81'			f-M sand	
	"	85'	86'			M sand	
	"	90'	91'			M sand	
	"	95'	96'			M sand	
	"	100'	100'			f sand & Clay	
	"	105'	106'			f-sand	
	"	110'	111'			f-sand	
	"	115'	116'			f-M sand	
	"	120'	121'			f-M sand w/ gravel	
	"	125'	126'			C sand w/ gravel	
	"	128'	129'			C sand w/ gravel	

RECEIVED

JUN 05 2002

Dept. of Environmental Quality
Office of Land & Water Resources

LMM 650
JAN '64