



556

Coahoma Co.  
G36

# FIELD BORING LOG

PROJECT Hillhouse Relief Wells

HOLE NO. 10

DRILL RIG Franks

SHEET 1 OF 1

LOCATION REMA LAGO MS

DEPTH OF WATER 11.0

DATE 5/04/02

INSPECTOR \_\_\_\_\_

OPERATOR \_\_\_\_\_

ELEVATION OF GROUND 152.13

TABLE \_\_\_\_\_

DATE 5/04/02

MUD None

Sample Number	Date	Sample		Stratum		Classification - Remarks	Type Sampler
		From	To	From	To		
	5/04	20'	21'			f sand	
	"	25'	26'			f sand	
	"	30'	31'			f sand	
	"	35'	36'			f sand	
	"	40'	41'			f sand	
	"	45'	46'			f sand	
	"	50'	51'			M sand	
	"	55'	56'			M sand	
	"	60'	61'			M w/ c sand	
	"	65'	66'			M sand w/ c sand	
	"	70'	71'			M sand w/ c sand	
	"	75'	76'			c sand	
	"	80'	81'			c sand	
	"	85'	86'			c sand	
	"	90'	91'			c sand	
	"	95'	96'			c sand	
	"	100'	101'			c sand w/ gravel	
	"	105'	106'			c sand w/ gravel	
	"	110'	111'			M sand	
	"	115'	116'			c sand	
	"	120'	121'			c sand w/ gravel	
	"	125'	126'			f sand w/ gravel	
	"	129'	130'			f sand	

**RECEIVED**

JUN 05 2002

Dept. of Environmental Quality  
Office of Land & Water Resources

LMM 650  
JAN '64