

COPY 1/1

878
1/13/73

I think this is
uses # B2

703
3/98

MISSISSIPPI
BOARD OF WATER COMMISSIONERS

416 North State Street
Jackson, Mississippi 39201

MS6W-12835

WATER WELL DRILLERS LOG

Hinds
B2
9-4-68
Miss. Geol. Surv.

9-4 1968 Levee-Central Company Hinds
date well completed firm name county well located

| LANDOWNER: | description of formations encountered | from | to |
|---|---------------------------------------|------------|------------|
| Reedtown Water Association | | | |
| <u>Utica, Miss.</u> (mailing address) | <u>Top Soil</u> | <u>0</u> | <u>5</u> |
| | <u>Yellow Clay</u> | <u>5</u> | <u>10</u> |
| | <u>Blue Clay</u> | <u>10</u> | <u>60</u> |
| | <u>Sand</u> | <u>60</u> | <u>82</u> |
| | <u>Shale streaks of sand</u> | <u>82</u> | <u>105</u> |
| | <u>Sand</u> | <u>105</u> | <u>112</u> |
| | <u>Shale streaks of sand</u> | <u>112</u> | <u>140</u> |
| | <u>Sand</u> | <u>140</u> | <u>175</u> |
| | <u>Shale streaks of sand</u> | <u>175</u> | <u>188</u> |
| | <u>Sand</u> | <u>188</u> | <u>249</u> |
| | <u>Shale</u> | <u>249</u> | <u>254</u> |
| WELL LOCATION: <u>Highway 18</u> | | | |
| sec. <u>7</u> T. <u>2</u> R. <u>4</u> E. <u>NW 1/4 NE 1/4</u> | | | |
| <u>5</u> miles <u>South</u> of <u>Utica</u> | | | |
| (distance) (direction) (nearest town) | | | |
| WELL PURPOSE: <u>Domestic</u> | | | |
| (home, irrigation, municipal, industrial) | | | |
| WELL COMPLETION DATA: | | | |
| (1) diameter (inches) <u>10"</u> | | | |
| (2) total depth (feet) <u>254'</u> | | | |
| (3) static water level (feet) <u>3</u> below top of ground. | | | |
| (4) casing <u>Steel</u> , <u>139'</u> (material) (depth) | | | |
| <u>10"</u> <u>7 7/8"</u> (size) (if telescope see back) | | | |
| (5) screen <u>50'</u> , <u>200'</u> (length) (depth to top) | | | |
| <u>6"</u> , <u>Stainless Steel</u> (size) (material) | | | |
| (6) pump <u>25</u> (HP) (yield gpm) | | | |
| <u>Electric</u> (type power) | | | |
| (7) electric log <u>yes</u> (yes or no) | | | |
| <u>Miss. Geol. Survey</u> (organization running log) | | | |
| (8) how well bottom plugged | | | |
| DRILLERS REMARKS: | | | |
| <u>Pump not installed</u> | | | |
| <u>as of this date</u> | | | |

CODED

SEP 17 1968
MISS. BOARD OF
WATER COMM.