

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
 Office of Land and Water Resources
 P. O. Box 2309
 Jackson, MS 39225
Water Well Plugging/Decommissioning Form
 OLWR-DF-1 (04/08)
 (601)961-5555 (601)961-5228 (fax)

RECEIVED
 APR 12 2021
 BY OLWR


COUNTY WELL LOCATED: Desoto		WELL NUMBER: #4 H80 BY	
PERMIT NUMBER: MS-GW-14626		DATE WELL PLUGGED: 3/18/2021	
NAME OF FIRM PLUGGING WELL: Donald Smith Company, Inc.		TELEPHONE NUMBER: 662-767-9777	
NAME AND ADDRESS OF CURRENT LANDOWNER: Lewisburg Water Association, 2787 Hwy 305 North, Olive Branch, MS 38654			
WELL LOCATION: SECTION: TOWNSHIP: RANGE:			
WELL LOCATION: LATITUDE: 34° 54' 10.56" N		LONGITUDE: 89° 49' 51.52" W	
METHOD (Check ONE): <input type="checkbox"/> USGS QUAD <input checked="" type="checkbox"/> CONVENTIONAL SURVEY <input checked="" type="checkbox"/> GPS - HAND HELD OR SURVEY GRADE			
DISTANCE: 3 Miles DIRECTION: South NEAREST TOWN: Olive Branch OTHER LANDMARK:			
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Rural Water Association			
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL: Herndon Well & Supply Inc. Shannon, MS			
NAME OF LANDOWNER WHEN WELL WAS DRILLED: Lewisburg Water Association			

WELL DATA			
WELL DEPTH: 246'		HOLE DEPTH: 246'	
CASING DIAMETER (IN.): 12"	CASING LENGTH (FT.): 206'	TYPE OF CASING: Steel	
DEPTH TO STATIC WATER LEVEL: 81'		DATE WELL COMPLETED: 12/7/1989	
WHY IS THE WELL BEING ABANDONED? Not needed			

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)

Removed pump from well.
 Casing and screen left intact.
 Ran 2" tremie line to top of screen.
 Pumped 170 sacks of neat cement.

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.

Mike Holloway <hr/>  SIGNATURE	UNR-00000787 <hr/> MS LICENSE NUMBER 3/22/2021 <hr/> DATE
---	--