


**MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY**  
**Office of Land and Water Resources**  
**P. O. Box 2309**  
**Jackson, MS 39225**  
**Water Well Plugging/Decommissioning Form**  
**OLWR-DF-1 (04/08)**

COUNTY WELL LOCATED: Desoto		WELL NUMBER: J GRID
PERMIT NUMBER: MS-GW-03506	DATE WELL PLUGGED: 7-16-2010	
NAME OF FIRM PLUGGING WELL: Irrigation Equipment Inc	TELEPHONE NUMBER: 662-887-2555	
NAME AND ADDRESS OF CURRENT LANDOWNER: Rodney & Linda Bohlender 12050 Parker Road Dalhart TX 79022 806-282-3142		
WELL LOCATION:	SECTION: 18	TOWNSHIP: 4S RANGE: 9W
WELL LOCATION: LATITUDE:	LONGITUDE:	METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY (3) GPS - HAND HELD OR SURVEY GRADE
DISTANCE:	DIRECTION:	NEAREST TOWN: Tunica OTHER LANDMARK:
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.):	Irrigation	
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:		
NAME OF LANDOWNER WHEN WELL WAS DRILLED:		

WELL DATA		
WELL DEPTH: 75'	HOLE DEPTH:	
CASING DIAMETER (IN): 10	CASING LENGTH (FT):	TYPE OF CASING: steel
DEPTH TO STATIC WATER LEVEL: 35'	DATE WELL COMPLETED:	
WHY IS THE WELL BEING ABANDONED?		

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)
Removed casing below ground level. Installed 0.7 gallon of 5% chlorine bleach. Installed sand and gravel. Installed bentonite and backfilled.
Note: New well drilled GW44442
New well is 25' west of plugged well.

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.	
Patrick M Chism	0695
	MS LICENSE NUMBER
PRINT NAME	7-26-2010
SIGNATURE	DATE

**RECEIVED**  
**JUL 28 2010**  
**BY: OLWR**

