

MISSISSIPPI
 BOARD OF WATER COMMISSIONERS
 416 North State Street
 Jackson, Mississippi 39201

WATER WELL DRILLERS LOG

Franklin
E 9013
9-1-79
Sept-1 1979

Reems Well Co Franklin
 firm name county well located

LANDOWNER:	description of formations encountered	from	to
<u>Charince King</u>			
<u>Rt. McCall Creek</u> (mailing address)	<u>small gravel</u>	<u>20</u>	<u>70</u>
WELL LOCATION:	<u>sand rock</u>	<u>70</u>	<u>91</u>
sec. <u>16</u> T. <u>7</u> N R. <u>5</u> E	<u>chalky sand</u>	<u>91</u>	<u>90</u>
<u>5</u> miles <u>8</u> north of <u>McCall</u>	<u>hard rock</u>	<u>90</u>	<u>93</u>
(distance) (direction) (nearest town)	<u>small gravel</u>	<u>93</u>	<u>102</u>
WELL PURPOSE: <u>house</u> (home, irrigation, municipal, industrial)			
WELL COMPLETION DATA:			
(1) diameter (inches) <u>4"</u>			
(2) total depth (feet) <u>102</u>			
(3) static water level (feet) <u>85</u> below top of ground.			
(4) casing <u>plastic bottom</u> (material) (depth)			
(size) If telescope see back.			
(5) screen <u>5'</u> <u>97'</u> (length) (depth to top)			
<u>4"</u> <u>plastic</u> (size) (material)			
(6) pump <u>1/2</u> <u>others</u> (HP) (yield gpm)			
<u>elect</u> (type power)			
(7) electric log <u>no</u> (yes or no)			
(organization running log)			
(8) how well bottom plugged <u>water plug</u>			
DRILLERS REMARKS: <u>@thers Failed</u> <u>hard sand rock</u>			

DEPT. OF NATURAL RESOURCES
 BUREAU OF LAND & WATER RESOURCES

JUN 25 1980

RECEIVED