

MISSISSIPPI DEPARTMENT OF NATURAL RESOURCES

Bureau of Land and Water Resources

Southport Mall

P.O. Box 10631

Jackson, Mississippi 39209

WATER WELL DRILLERS LOG

Franklin
K 2019

July 8, 1981 Reynolds Well Inc Franklin
date well completed firm name county well located

LANDOWNER:	description of formations encountered	from	to
<u>George Hunter</u> <u>Rt McCall Creek</u> (mailing address)	<u>clay</u> <u>sand gravel</u> <u>blue chalk</u>	<u>2</u> <u>16</u> <u>77</u>	<u>16</u> <u>77</u> <u>135</u>
WELL LOCATION: sec <u>30</u> T <u>6</u> N R <u>6</u> E <u>4</u> miles <u>South</u> of <u>Lucion</u> (distance) (direction) (nearest town)	<u>fine blue sand</u> <u>coarse sand</u>	<u>135</u> <u>145</u>	<u>145</u> <u>154</u>
WELL PURPOSE: <u>home</u> (home, irrigation, municipal, industrial)			
WELL COMPLETION DATA:			
(1) diameter (inches) <u>4"</u>			
(2) total depth (feet) <u>154</u>			
(3) static water level (feet) <u>115</u> below top of ground.			
(4) casing <u>plastic, 154 ft</u> (material) (depth) <u>5</u> if telescope see back. (size)			
(5) screen <u>5</u> , <u>149'</u> (length) (depth to top)			
(6) pump <u>4</u> <u>plastic</u> (size) (material)			
(6) pump <u>3/4</u> <u>12</u> (HP) (yield gpm)			
(6) pump <u>electric</u> (type power)			
(7) electric log <u>no</u> (yes or no)			
(organization running log)			
(8) how well bottom plugged <u>backwash valve</u>			
DRILLERS REMARKS:			

DEPT. OF NATURAL RESOURCES
BUREAU OF LAND & WATER RESOURCES

FEB - 8 1982
RECEIVED