


K
11-16-61

WATER WELL DRILLERS LOG

3

Date: 11-16, 1961, Driller: Sutter Well Works County Hancock
(Name)

	Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
(1) Owner of Land: <u>H. F. Parker</u>			
(Name)			
<u>6129 TCHOUPILOUAS ST. - N.D.L.A.</u>	<u>clay</u>	<u>10</u>	<u>10</u>
(Address)	<u>sand + gravel</u>	<u>30</u>	<u>40</u>
(2) Location: <u>SW 1/4, SW 1/4, Sec. 42 T8S R 14W</u>	<u>clay</u>	<u>68</u>	<u>108</u>
	<u>sand</u>	<u>42</u>	<u>150</u>
<u>5</u> miles <u>NW</u> of <u>BAY ST.</u>			
(distance) (direction) (Nearest Twn)			
(3) Topography: <u>flat</u>			
(Hilly) (Flat) (Level)			
(4) Purpose of Well: <u>domestic home</u>			
(Domestic Irrigation Municipal, Industrial, Other)			
Information upon completion of well:			
(1) Diameter <u>1 1/4</u> inches.			
(2) Total Depth <u>150</u> feet.			
(3) Water Level <u>flow</u> feet below top of ground.			
(4) Cased to <u>see</u> , Size <u>1 1/4"</u>			
(5) Screen: Size <u>1 1/4"</u> , Length <u>5'</u>			
(6) Were any formations sealed against pollution?			
_____ yes, <input checked="" type="checkbox"/> no.			
If YES depth of formation _____			
Why _____			
Drillers Remarks: _____			



Well No.

1. 1000

2. 1000

3. 1000

4. 1000
5. 1000
6. 1000
7. 1000

8. 1000
9. 1000
10. 1000

11. 1000
12. 1000
13. 1000

14. 1000

15. 1000

16. 1000

17. 1000

18. 1000

19. 1000

20. 1000

21. 1000

22. 1000

23. 1000

24. 1000

25. 1000

26. 1000

27. 1000

28. 1000

29. 1000

30. 1000