

**RAYBORN DRILLING & CONSTRUCTION**  
Telephone 445-8930 Route 5, Box 98  
NATCHEZ, MISSISSIPPI 39120

February 2, 1987

Alford Engineering  
Post Office Box 16621  
Jackson, MS 39236-0921

Attention: Mr. S.F. Alford, III

Dear Mr. Alford:

Please see below the driller's formation log for the test hole drilled at Site # 4 on January 30, 1987:

LOCATION: NE $\frac{1}{4}$ -NE $\frac{1}{4}$  Sec. 31 T3N R4W  
Hinds County

<u>FORMATION DESCRIPTION</u>	<u>DEPTH FROM FEET</u>	<u>DEPTH TO FEET</u>
Top Soil	0	20
Clay	20	40
Clay/Rock	40	60
Clay	60	120
Clay/Sand	120	140
Clay	140	160
Sand	160	180
Sand/Clay	180	200
Clay	200	220
Sand/Clay	220	240
Clay	240	320
Clay/Sand	320	360
Sand/Clay/Lignite	360	380
Clay/Rock	380	420
Sand/Rock	420	440
Clay/Rock	440	460
Rock	460	500

Thank you for your attention to this matter.

Sincerely,

Raymond N. Nettles  
General Manager

RNN/ltr