

Suddoth Pivot

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
Office of Land and Water Resources
P. O. Box 2309
Jackson, MS 39225
Water Well Plugging/Decommissioning Form
OLWR-DF-1 (04/08)

no drill log

COUNTY WELL LOCATED: COAHOMA		WELL NUMBER: B	
PERMIT NUMBER: GW-06144	DATE WELL PLUGGED: 7-15-19		
NAME OF FIRM PLUGGING WELL: Massey Planting Co	TELEPHONE NUMBER: 662-902-6215		
NAME AND ADDRESS OF CURRENT LANDOWNER:			
WELL LOCATION: SE 1/4 of NE 1/4	SECTION: 09	TOWNSHIP: 28N	RANGE: 03W
WELL LOCATION: LATITUDE:	LONGITUDE:	METHOD (Check ONE): <input type="checkbox"/> USGS QUAD <input type="checkbox"/> CONVENTIONAL SURVEY <input checked="" type="checkbox"/> GPS - HAND HELD OR SURVEY GRADE	
DISTANCE:	DIRECTION:	NEAREST TOWN:	OTHER LANDMARK:
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Irrigation			
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:			
NAME OF LANDOWNER WHEN WELL WAS DRILLED: Ellington & Massey			

RECEIVED
SEP 05 2019
BY OLWR

WELL DATA			
WELL DEPTH:		HOLE DEPTH:	
CASING DIAMETER (IN.): 12"	CASING LENGTH (FT.):	TYPE OF CASING: Steel	
DEPTH TO STATIC WATER LEVEL: 20'	DATE WELL COMPLETED: 1987		
WHY IS THE WELL BEING ABANDONED? Sucking Sand & Motor Sinking			

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)

As this was a Agricultural well for Center Pivot, It was decommissioned as procedure (6d).

The steel well casing was cut off more than 3 ft below the surface, then it was capped off with a plastic barrel, then it was covered with compacted soil.

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.

B Turner Massey
PRINT NAME

B Turner Massey
SIGNATURE

MS LICENSE NUMBER

9-2-19
DATE