

amba

BA

# GROUNDWATER WELL DRILLERS LOG

62  
4-16  
5

1962 Driller: Eotis  
Herndon (Name - Haman?)

DeWitt  
County Attala

(1) Owner of Land: Lee Hall Haman  
(Name)  
Carolina Trust  
(Address)

(2) Location: NF 1/4, SW 1/4, Sec 20 T119 R24  
\_\_\_\_\_ miles \_\_\_\_\_ of \_\_\_\_\_  
(distance) (direction) (Nearest Town)

(3) Topography: \_\_\_\_\_  
(Hilly) (Flat) (Level)

(4) Purpose of Well: Industrial  
(Domestic Irrigation  
Municipal, Industrial, Other)

Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
<u>Red sand to 40 ft</u>		
<u>to 100 ft is</u>		
<u>Beninite</u>		
<u>100-123 sand +</u>		
<u>gravel</u>		
<u>123-Blue Clay</u>		
<u>123-165 sand</u>		
<u>165-228 Rock</u>		
<u>228-270 sand</u>		
<u>270-329 gravel</u>		

### Information upon completion of well:

(1) Diameter: 5 inches.

(2) Total Depth: 329 feet.

(3) Water Level: 75 feet below top of ground.

(4) Cased to: 123, Size 5"

(5) Screen: Size \_\_\_\_\_, Length \_\_\_\_\_

(6) Were any formations sealed against pollution?  
 yes, \_\_\_\_\_ no.

If YES depth of formation 123

Why \_\_\_\_\_

Drillers Remarks: \_\_\_\_\_

\_\_\_\_\_

I 26



Well No.

Mail this copy to Board of Water Commissioners 429 Miss. St. Jackson, Miss.