

LAUD. MISSISSIPPI BOARD OF WATER COMMISSIONERS


Ø60  
11-16-63

WATER WELL DRILLERS LOG

**CODED**

Date 11/16, 1963, Driller: M. E. Donald & Hill, Inc Landersdale  
(Name)

		Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
(1) Owner of Land: <u>H. Hollingsworth</u> (Name)				
<u>Rt 6, mendon, miss</u> (Address)		<u>CLAY</u>	<u>0</u>	<u>20</u>
		<u>SHALE</u>	<u>20</u>	<u>58</u>
(2) Location: <u>1/4, 1/4, Sec. 17 &amp; 17</u> (distance) (direction) (Nearest Town)		<u>LIME ROCK</u>	<u>58</u>	<u>62</u>
		<u>SHALE</u>	<u>62</u>	<u>110</u>
		<u>SANDY SHALE</u>	<u>110</u>	<u>140</u>
		<u>SHALE</u>	<u>140</u>	<u>205</u>
(3) Topography: <u>X</u> (Hilly) (Flat) (Level)		<u>SANDY</u>	<u>205</u>	<u>220</u>
(4) Purpose of Well: <u>DOMESTIC</u> (Domestic Irrigation Municipal, Industrial, Other)		<u>SANDY</u>	<u>220</u>	<u>280</u>



**CODED**

Information upon completion of well:

- (1) Diameter 4" inches.
- (2) Total Depth 280' feet.
- (3) Water Level 90' feet below top of ground.
- (4) Cased to 108', Size 4"
- (5) Screen: Size \_\_\_\_\_, Length \_\_\_\_\_
- (6) Were any formations sealed against pollution?  
\_\_\_\_\_ yes, \_\_\_\_\_ no.
- If YES depth of formation \_\_\_\_\_
- Why \_\_\_\_\_
- Drillers Remarks: \_\_\_\_\_

(Use Back Side)

Well No.

Mail this copy to Board of Water Commissioners 429 Miss. St. Jackson, Miss.