

MISSISSIPPI DEPARTMENT OF NATURAL RESOURCES
 Bureau of Land and Water Resources
 Southport Mall
 P.O. Box 10631
 Jackson, Mississippi 39209
WATER WELL DRILLERS LOG

LEAKE
G
2013

1-15-86 19 F.O. Camors Leake
 date well completed firm name county well located

LANDOWNER:	description of formations encountered	from	to
<u>Jimmy Howell</u>			
(mailing address)	<u>sand</u>	<u>20</u>	<u>50</u>
	<u>Hard sand</u>	<u>50</u>	<u>50</u>
	<u>Red sand</u>	<u>70</u>	<u>85</u>
WELL LOCATION:			
sec. <u>30</u> <u>11</u> <u>N</u> <u>80</u> <u>W</u>			
<u>2</u> miles <u>N</u> of <u>Cortage</u>			
(distance) (direction) (nearest town)			
WELL PURPOSE:			
<u>Home</u> Irrigation, municipal, Industrial			
WELL COMPLETION DATA:			
(1) diameter (inches) <u>2 1/2</u>			
(2) total depth (feet) <u>85'</u>			
(3) static water level (feet) <u>60'</u> below top of ground.			
(4) casing <u>2"</u> <u>86'</u> (material) (depth)			
<u>2"</u> If telescope see back. (size)			
(5) screen <u>2"</u> <u>p.v.c. 96</u> (length) (depth to top)			
<u>2' x 10'</u> <u>p.v.c.</u> (size) (material)			
(6) pump <u>1</u> <u>220 GPH</u> (HP) (yield-gpm)			
<u>Electric</u> (type power)			
(7) electric log <u>NO</u> (yes or no)			
<u>Sandhurst</u> (organization running log)			
(8) how well bottom plugged _____			
DRILLERS REMARKS:			

RECEIVED
 JAN 27 1986

Department of Natural Resources
 Bureau of Land & Water Resources