MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY Office of Land and Water Resources P. O. Box 2309 Jackson, MS 39225 Water Well Plugging/Decommissioning Form OLWR-DF-1 (04/08)

COUNTY WELL LOCATED: Roundes		WELL NUMBER: 0876242			
PERMIT NUMBER:	DATE WELL PLUGGE	· 2/12/16			
NAME OF FIRM PLUGGING WELL: Clardy Drillon		662-328-3168			
NAME AND ADDRESS OF Smith Sanda Caping 3970 CURRENT LANDOWNER: 604 18th ave. J., Columbus, JNS					
WELL LOCATION: SECTION: 9 TOWN	SHIP: 185 RANGE:	18W			
WELL LOCATION: LATITUDE: LONGITUDE: METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY					
DISTANCE: TO DIRECTION: CITYNEAREST TOWN TO OTHER LANDMARK:					
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.):					
NAME OF WELL CONTRACTOR Clardy Drilling					
NAME OF LANDOWNER WHEN WELL WAS DRILLED: Smith Band	ecapin	B			
w	ELL DATA				

		WELL DATA			
WELL DEPTH:	182'		HOLE DEPTH:	182'	
CASING DIAMETER (IN.):	CASING LENGTH (FT.):	2' 82'	TYPE OF CASING:	YC	
DEPTH TO STATIC WATER LEVEL:	171/2	DATE WELL COMP		30195	
WHY IS THE WELL BEING ABANDONE		morio	Unaucot	5	
			-0		

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)
mattal at new concercionant
and Silvage of comments grouts was
pumped ito surface. all the casing
you and the unitererused. The toplate
the my of man cut off 3' welow D
the around years the most day.

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN AC	
Dow Clardy	UNR-00000 496
De TOP PRINT NAME	MS LICENSE NUMBER
SIGNATURE) DATE

FEB 1 7 2016