

D.I.

8-19-60

Date: Aug 19, 1960, Driller: Braswell Drilling Co. County: Montgomery

(Name)

(1) Owner of Land: E. B. Jarratt (Name)

Duck Hill, Missa (Address)

(2) Location: W 1/2 NE 1/4 Sec 5 T 28 N R 6 E

2 miles SE of Duck Hill (distance) (direction) (Nearest Town)

(3) Topography: Hilly (Hilly) (Flat) (Level)

(4) Purpose of Well: Domestic (Domestic Irrigation Municipal, Industrial, Other)

Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
Red Clay	21	21
White Chalk	125	126
Very gummy		
Sand & dirt streaks	65	189
Hard shale	147	336
Fine silt	63	399

Information upon completion of well:

(1) Diameter 2 inches.

(2) Total Depth 399 feet.

(3) Water Level 35 feet below top of ground.

(4) Cased to 138 + 105' of 1 1/2" Size 2"

(5) Screen: Size 90 yds, Length 10'

(6) Were any formations sealed against pollution?
yes, no. [check]

If YES depth of formation

Why

Drillers Remarks: This should be good water and last many years.



This CODED

This Chalk has possibilities of Commercial Value

(Use Back Side)

Well No.

