

PANOLA

MISSISSIPPI BOARD OF WATER COMMISSIONERS

M L 2  
7-10-60

WATER WELL DRILLERS LOG

CODED

Date 7/10, 1960, Driller James R Lize County Panola

(Name)

(1) Owner of Land	Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
<u>Melrose Baptist Church</u> (Name) <u>Dandis, Miss.</u> (Address)	<u>Clay</u>	<u>40</u>	<u>0-40</u>
(2) Location: <u>1/4</u> , <u>1/4</u> , Sec. <u>8</u> T <u>8</u> R <u>8</u> W <u>1</u> miles <u>SW</u> of <u>Sandis</u> (distance) (direction) (Nearest Town).	<u>Gravel</u> <u>Blue Clay</u> <u>with bearing sand</u>	<u>60</u> <u>70</u> <u>18</u>	<u>100</u> <u>170</u> <u>188</u>
(3) Topography: <input checked="" type="checkbox"/> (Hilly) <input type="checkbox"/> (Flat) <input type="checkbox"/> (Level)			
(4) Purpose of Well: <u>Church</u> (Domestic Irrigation Municipal, Industrial, Other)			

CODED

Information upon completion of well:

(1) Diameter 2 1/2 inches.

(2) Total Depth 188 feet.

(3) Water Level 140 feet below top of ground.

(4) Cased to 188, Size 2 1/2.


(5) Screen: Size 1 1/2, Length 6.

(6) Were any formations sealed against pollution?  
 yes,  no.

If YES depth of formation \_\_\_\_\_

Why \_\_\_\_\_

Drillers Remarks: \_\_\_\_\_



(Use Back Side)

Well No.

