

CODED

Panola
R 30
11-3-69

MISSISSIPPI
BOARD OF WATER COMMISSIONERS
416 North State Street
Jackson, Mississippi 39201

WATER WELL DRILLERS LOG

LIPE WELL CO. PANOLA

date well completed 19 firm name county well located

| LANDOWNER: | description of formations encountered | from | to |
|--|---------------------------------------|------|-----|
| Susie Taylor | | | |
| Batesville Miss. (mailing address) | sand | 20 | 40 |
| WELL LOCATION: | gravel | 40 | 60 |
| sec 21 T 9 N R 7 E | gravel | 60 | 80 |
| 2 miles S of Batesville | sand | 80 | 100 |
| (distance) (direction) (nearest town) | sand | 100 | 120 |
| WELL PURPOSE: home | sand | 120 | 140 |
| (home, irrigation, municipal, industrial) | sand | 140 | 160 |
| WELL COMPLETION DATA: | | | |
| (1) diameter (inches) 4" | | | |
| (2) total depth (feet) 160' | | | |
| (3) static water level (feet) _____ below above top of ground. | | | |
| (4) casing PVC 152' (material) (depth) | | | |
| 4" (size) if telescope see back. | | | |
| (5) screen 8' 152' (length) (depth to top) | | | |
| 4" PVC + silica (size) (material) | | | |
| (6) pump 3/4 10 (HP) (yield gpm) | | | |
| electric (type power) | | | |
| (7) electric log NO (yes or no) | | | |
| (organization running log) | | | |
| (8) how well bottom plugged: PVC cap | | | |
| DRILLERS REMARKS: | | | |

NOV 8 - 1969



